MS-74A / MX-53A / MF-53A / ML-53A

INSTRUCTION MANUAL

Heat Drying Moisture Analyzer

MS-74A

MX-53A

MF-53A

ML-53A



Notation for Precautions

Meaning of Warning Signs

△WARNING	Indicates information where incorrectly handling the product may lead to death or serious injury.
∆ CAUTION	Indicates information where incorrectly handling the product may lead to injury or damage to property.

Meaning of Symbols

The 🌓 symbol indicates an action that is required.
Details on the action are indicated inside the [] or in nearby documents or
pictures.

Other

CAUTION	Indicates cautionary information regarding the correct use of the product.
ADVICE	Indicates general advice regarding the use of the product and what to do when a mistake is made.
	Indicates a high temperature caution.

CAUTION

- (1) This instruction manual (hereinafter "this manual") may not be copied, duplicated, modified, or translated, in full or in part, without the written permission of A&D Company, Limited (hereinafter "A&D").
- (2) The content of this manual is subject to change without notice.

their respective owners in Japan and other countries.

- (3) If you have any questions regarding the content of this manual or notice any errors or missing information, please contact A&D.
- (4) A&D shall assume no responsibility for any direct, indirect, special, or consequential damages arising due to flaws in the product or damages or loss of profit caused by the use of the product, even if it is notified of the possibility of those damages occurring in advance. A&D shall also assume no responsibility for claims of rights by third parties. A&D shall assume no responsibility for the loss of any software or data.

©2025 A&D Company, Limited

Microsoft®, Windows®, Word®, and Excel® are trademarks of the Microsoft Group.
The Bluetooth® word mark and logos are registered trademarks owned by Bluetooth SIG, Inc. and any
use of such marks by A&D is under license.
Other product names and company names in this manual are trademarks or registered trademarks of

Contents

1.	Cautio	ons Regarding Handling	6
	1.1.	Cautions Regarding Installation	7
	1.2.	Cautions Regarding Use	8
	1.3.	Cautions After Use and Cautions Regarding Storage	11
2.	Produ	ct Overview/Features	12
3.	Conte	nt of Package and Names of Parts	14
	3.1. k	Cey Switches and Indicators	16
4.	-	rements for Preparing to Measure (Installation, Initial Configuration, and Measurement)	
		nstalling the Moisture Analyzer	
		Requirements for Ensuring Correct Measurement	
	4.2.1.	Handling Samples	
	4.2.2.	Requirements for the Operation Procedure	
	4.2.3.	How to Use the Preheat Function	22
	4.2.4.	Using a Glass Fiber Sheet	24
5.	Meas	urement	27
	5.1. F	Procedure for Measuring the Moisture Content	27
6.	Meas	urement Conditions	31
	6.1. H	low to Select a Program Number	32
		xample Measurement Conditions	
	6.2.1.	List of Example Measurement Conditions and Actual Measurement Results	
	6.2.2.	How to Use Example Measurement Conditions	
	6.3.	Overview of Measurement Conditions	
	6.3.1.	List of Measurement Conditions	
	6.3.2.	Available Measurement Conditions	
	6.3.3.	Default Setting	
	6.4. E	Detailed Description of Measurement Conditions	
	6.4.1.	How to Select Measurement Conditions	
	6.4.2.	Measurement Modes	
	6.4.3.	Heating Pattern	
	6.4.4.	Temperature and Time	
	6.4.5.	Measurement Accuracy	
	6.4.6.	Termination value	
	6.4.7.	Configuring the Sample Mass	
	6.4.8.	Measurement Basis	
	6.4.9.	Minimum Displayed (Percentage/Grams)	
	6.4.10		
	6.4.11	·	
	6.4.12		
		examples of Changing the Measurement Conditions	
	6.5.1.	Example 1 (Standard Conditions)	
	6.5.2.	Example 2 (Complex Conditions)	

7. Fur	nction Tests and Adjustment	80
7.1.	Function Tests and Adjustment Modes	80
7.2.	Test Sample Function Check	81
7.3.	RS TEMP (Heating Temperature Detection Function)	83
7.4.	Self-Inspection	
7.5.	Adjusting the Sensitivity of the Mass Sensor	
7.6.	Adjusting the Heating Temperature	91
8. Inte	ernal Settings	95
8.1.	Procedure	95
8.2.	List of Items	98
8.3.	Description of Environment/Display Settings	100
8.4.	Checking and Configuring the Date/Time	101
8.5.	Additional Functions for Measurement Conditions	106
8.6.	Description of Data Output	107
8.6	5.1. Data Output Mode	107
8.6	5.2. Data Format	108
8.6	3.3. Example Output for Data Format	109
9. GL	P and ID Numbers	111
9.1.	Main Uses	111
9.2.	Configuring the ID Number	112
9.3.	GLP output	114
9.3	5.1. Example Measurement Result Output	116
9.3	3.2. Description of Printed Information	123
9.3	3.3. Test Sample Output for Function Check	126
9.3	Mass Sensor Output for Sensitivity Adjustment	127
9.3	5.5. Output for Heating Temperature Adjustment	128
10. Da	ıta Memory Function	129
10.1.	Preparations	129
10.2.	Batch Output of Recorded Results	131
10.3.	Batch Erasure of Recorded Results	133
11 Pa	ssword Function	135
11.1.	Preparing the Password Function	
11.2.	Registering (Changing) the Password	
11.3.	How to Log In	
11.4.	How to Log Out	
11.5. 11.6.	How to Delete a User (USER) Password If the Administrator (ADMIN) Password Is Forgotten	
	•	
12. Inte	erface Specifications	
12.1.		
12.2.	RS-232C	149
13. Co	nnecting to a Peripheral	150
13.1.	Cables Used for Connecting to a Peripheral	150
13.2.		

13.2	2.1. For the AD-8127 or AD-8129TH	151
13.3.	Connecting to a Computer	152
13.3	3.1. Virtual COM Mode	152
13.3	3.2. Quick USB Mode	157
13.3	3.3. RS-232C	161
13.4.	WinCT-Moisture Communication Software	162
13.4	I.1. RsFig Graph Software for Moisture Content Measurement	162
13.4	I.2. RsTemp Software for Automatic Heating Temperature Detection	163
13.5.	WinCT Data Communication Software	165
13.6.	Commands	166
14. Hov	v to Check the Software Version of the Moisture Analyzer	167
15. Maii	ntenance	168
15.1.	Cleaning the Heater	168
15.2.	How to Replace the Halogen Lamp	169
15.3.	How to Replace the Power Fuse	. 171
15.4.	Initializing the Settings	. 172
15.4	I.1. How to Initialize (Internal Settings)	. 173
15.4	I.2. How to Initialize (All Settings)	175
15.5.	Troubleshooting	. 177
15.6.	Errors Displayed	178
16. Disp	posal	180
17. Spe	ecifications	181
17.1.	External Dimensions	183
18. Acc	essories (Sold Separately)	. 184

Cautions Regarding Handling

Safety Information ()



This product is a moisture analyzer based on the principles of thermal mass analysis. It measures properties such as the moisture content and solids in a sample based on changes in mass caused by heating and drying the sample with a halogen lamp to vaporize the moisture. Do not use it for other purposes.

This manual contains basic information on handling the product. Read it thoroughly before using the product.

The product is designed to be used by an experienced operator.

Using the product in a manner not described in this manual, such as modifying, disassembling, or misusing the product, may be dangerous.

A&D shall not be held responsible for this in any way.


1.1. Cautions Regarding Installation

MWARNING

Danger of death due to fire or explosion

- Perform measurement in an appropriate environment.
 - ☐ Do not use the product in a dangerous environment, such as in an atmosphere of flammable gas.
 - ☐ Ensure that the product is installed in an environment with the following temperature and humidity. Temperature: 5 to 40°C; Humidity: 85% or lower RH (without condensation)
 - □ Do not use the product in a poorly ventilated environment. Using the product in an environment that hinders the dissipation of heat from the moisture analyzer, such as a sealed environment, may cause unexpected rises in temperature or symptoms of poisoning.
- <u>A</u>Do not place flammable objects in the vicinity of the product.
 - ☐ The various parts of the moisture analyzer will be at a high temperature during measurement and immediately after measurement, and this can cause objects to catch fire.
 - Never place objects on the heater cover.
 - ☐ Do not operate the product with any cables or other objects on it.

Heater cover



MARNING

Danger of death or failure due to electrocution

Check the power supply voltage.

The compatible power supply voltage is indicated on the rear of the moisture analyzer.


Confirm that it matches the power supply voltage you are using.

Ground terminal


- When connecting the moisture analyzer to the power supply, use the included power cable.
- Ground the moisture analyzer. If the power outlet does not have a ground terminal, ground it with a ground adapter.

Beware of water leaks. The moisture analyzer is not waterproof.
 Electrocution or failure may occur if water enters the inside of the moisture analyzer.

Grounding Method
Grounding with the power



Grounding with a ground



↑ CAUTION

To ensure correct measurement

- Note the following regarding the high-accuracy electromagnetic balance type mass sensor used by the product.
 - ☐ Install the product on a robust platform (table).
 - Avoid vibrations.
 - ☐ Install the product in a location where it will not be exposed to air from an air conditioner, etc.

1.2. Cautions Regarding Use

↑ WARNING


Danger of death due to fire, explosion, or poisoning

- Do not measure dangerous samples.
 - □ Do not heat samples that are prone to explosion or combustion or heat samples that emit hazardous substances, as doing so is extremely dangerous. Samples with unknown properties are just as dangerous.
 - ☐ If the internal pressure of the sample rises because the surface dries first, the sample may rupture.

 Do not perform measurement in this case, as it is dangerous.
 - ☐ If the sample catches fire, immediately remove the power cable from the power outlet, and perform the appropriate procedures.

The case of the moisture analyzer uses flame-retardant material (UL94V-0).

- Do not place flammable objects in the vicinity of the product.
- The various parts of the moisture analyzer will be at a high temperature during measurement and immediately after measurement.
 Do not place flammable objects in the vicinity of the product, as doing so may cause a fire.
- Never place objects on the heater cover.



Heater cover




Danger of blindness

- Do not look directly at the halogen lamp during heating. Doing so may cause eye pain or vision problems.
- When performing measurement, wear appropriate protective gear, such as goggles and gloves.
- Do not modify or disassemble the moisture analyzer. Doing so may cause failure, electrocution, or fire. If you suspect that the product has failed, contact your place of purchase.
- Do not expose the moisture analyzer, power cable, or accessories to extreme temperatures, intense
 chemical vapors, humidity, impacts, vibrations, or strong magnetic fields. Follow the operating
 conditions listed in "17. Specifications".




▲Danger of burns caused by high temperature surfaces


- Make sure to follow the correct operation methods and procedures.
 - ☐ Make sure to place the breeze brake, tray holder, sample tray, and sample tray handle correctly.
 - ☐ Make sure to hold the heater cover handle when opening or closing the heater cover.



☐ The areas with diagonal lines will be at a high temperature during measurement. Only touch the heater cover handle and sample tray handle when operating the product.



□ Do not touch the high temperature parts such as the inside of the heater cover or sample tray with your hands immediately after heating. Doing so may cause burns. The product will be at a high temperature during measurement and immediately after measurement. When touching the moisture analyzer, make sure to use the specified handle and included tool, and avoid touching the glass housing and the glass and metal (aluminum) parts near the halogen lamp (heater).



- ☐ The aforementioned glass housing is at a particularly high temperature and can cause burns if you touch it directly.
- ☐ The sample tray and sample tray handle will be at a high temperature immediately after measurement. Cool them in an appropriate location. Use tweezers, etc. when grasping the sample tray.

ACAUTION

Danger of injury due to inappropriate handling

- Dispose of the used halogen lamp as-is.
 Breaking the halogen lamp can cause glass shards to scatter, which may result in injury.
- Do not drop, strike, or damage glass parts including the halogen lamp.
 Doing so may cause them to break and result in injury.
- The edges of the sample tray are sharp. Take care not to cut your hands.
- Make sure to hold the heater cover handle when opening or closing the heater cover, and take care not to get your hands caught.
- When moving the moisture analyzer, make sure it has cooled down and lift it directly up without tilting
 it.

Moving it tilted may cause the heater cover to unexpectedly open and result in injury.

ACAUTION

Danger of device failure due to inappropriate handling

- It is recommended that you replace the halogen lamp once it has reached its rated life (approx. 5,000 hours), as it may break.
- Do not drop, strike, or damage glass parts including the halogen lamp.
 Doing so may cause them to break.
- Do not allow dust or water to enter the inside of the moisture analyzer.
- Only use accessories and parts manufactured by A&D.
- If the moisture analyzer behaves in an unexpected manner, try removing the power cable from the power outlet and reconnecting it.
 - If the product still does not operate normally, request a repair.

CAUTION

- Caution regarding high temperature heating
 - Do not perform continuous heating for 30 minutes or longer with the product set to 200°C. The safety mechanism may cut the power supply to the halogen lamp.
 - For safety purposes, the high temperature setting is automatically lowered to 160°C if one hour elapses after heating starts.
- The STOP key is always available during measurement. If you suspect any problem or danger, immediately press the STOP key to stop measurement.

1.3. Cautions After Use and Cautions Regarding Storage

ACAUTION

▲Danger of burns caused by high temperature surfaces

- Perform operations after confirming that the various parts of the moisture analyzer have cooled down.
 - In particular, confirm that the area around the glass housing has cooled down before replacing the lamp.

Device Failure

- Do not allow dust or water to enter the inside of the moisture analyzer.
- When cleaning the product, use a cloth dampened with diluted neutral detergent. Do not use organic solvents or chemical wipes. Doing so may cause product failure.
- Make sure to remove the power plug from the power outlet before performing maintenance.
- When transporting the product, use the dedicated packaging box.

CAUTION

- Clean the glass housing if it gets dirty, or it may not be able to heat properly. For information on handling, refer to "15.1. Cleaning the Heater".
- Clean the halogen lamp if it has any fingerprints on it, or its life may be shortened.
 For information on handling, refer to the separate instruction manual.
- Do not subject the moisture analyzer to impacts or drop it, as doing so may damage the halogen lamp or mass sensor.
- Make sure to remove the power plug from the power outlet if the product will not be used for an extended period of time.

2. Product Overview/Features

- The product adopts an SHS (Super Hybrid Sensor), the mass sensor used in analytical scales, to enable measurement with high accuracy and high reproducibility.
- Because of its high measurement sensitivity, it only requires a small amount of sample, and this
 contributes to reduced measurement time.
- The product adopts a 400 W halogen lamp as its heater, which allows the tray temperature to reach 200°C within two minutes.
- The product has the following three measurement modes.

Standard mode This mode automatically measures moisture content by specifying the

measurement accuracy.

Timer mode This mode measures moisture content by heating for a certain period of time.

Custom mode This mode enables the user to configure detailed measurement conditions.

The product has the following four heating pattern.

Standard heating This mode maintains a constant heating temperature.

Slow heating This mode gradually raises the heating temperature.

Step heating This mode uses two heating temperatures.

Rapid speed heating This mode reduces the measurement time by heating at high temperature for a

certain period of time after measurement starts.

- 200 sets of optimal measurement conditions for various samples can be configured and recalled when performing measurement.
- More than 100 sets of example measurement conditions for various samples can be recalled when performing measurement.
- The moisture analyzer can store up to 200 measurement results and has a data memory function for the batch output of results.
- The dedicated WinCT-Moisture software has a function for the real-time graphing of changes in moisture content and a function for determining the appropriate heating temperature.
- You can also download the WinCT data communication software from the A&D website for easily importing data to a Windows computer.
- The product is equipped with USB and RS-232C interfaces as standard for easily connecting to a computer or printer.
- The product enables sensitivity adjustment of the mass sensor (use of the dedicated weight is recommended) and adjustment of the heater temperature (requires the dedicated temperature adjustment kit). When performing adjustment, data can be output in response to GLP/GMP/ISO requests.
- The product has a self-inspection function for checking the measurement results of a test sample and checking for electrical circuit and temperature control problems.
- The change in moisture content over time (%/min) during measurement is displayed in real-time. This
 can be used to help determine the termination value.
- The included sample tray is reusable. Disposable aluminum trays are also included as standard.
- The product has test samples for checking the accuracy of measurement. (Included with the MS-74A/MX-53A as standard.)


- The product has glass fiber sheets for precisely measuring liquid samples in a short time. (Included with the MS-74A/MX-53A as standard.)
- The product has a test mode for measuring the recommended value for the heating temperature (refer to "7.3. RS TEMP (Heating Temperature Detection Function)").

Principle and Intended Use

• The moisture analyzer is based on the principle of thermal mass analysis. It measures properties such as the moisture content and solids in a sample based on changes in mass by heating and drying the sample with a halogen lamp to vaporize the moisture.

3. Content of Package and Names of Parts


- Confirm that all the parts are included.
- Retain the packaging to use for transporting or repairing the product.



No.	Name	Material
1	Heater cover	PBT, PC, ABS
2	Heater cover handle	PBT
3	Display	
4	Leveler	
5	Keys	
6	Sample tray handle	SUS316, ABS
		Elastomer,
7	Foot adjuster	SUS
8	Fuse (T6.3 A 250 V)	
9	Power inlet	
10	RS-232C interface	
11	USB interface	
12	Disposable aluminum tray	

No.	Name	Material
13	Sample tray	Aluminum
14	Tray holder	SUS304, SUS316
15	Breeze break	SUS304 (galvanized)
16	Halogen lamp	
17	Glass housing	Glass,
17	Glass flousing	Aluminum die-cast
18	Serial number	
19	Floor panel for insulation	SUS304
20	Floor panel	PBT
21	Main unit upper case	ABS
22	Main unit lower case	Aluminum die-cast
	iviairi uriil lower case	(coated)

Accessories




No.	Name	MS-74A	MX-53A	MF-53A	ML-53A	Accessory number
23	Sample tray	× 20	× 20	× 10	× 10	AX-MXA-31
24	Tray holder	Yes	Yes	Yes	Yes	
25	Sample tray handle	× 2	× 2	× 1	× 1	AX-MXA-35
26	Breeze break	Yes	Yes	Yes	Yes	
27	Body cover	Yes	Yes	-	-	AX-MXA-39
28	Quick Start Guide	Yes	Yes	Yes	Yes	
29	Warranty card	Yes	Yes	Yes	Yes	
30	Display protective cover	Yes	Yes	Yes	Yes	AX-MXA-38
31	Power cable	Yes	Yes	Yes	Yes	
32	Ground adapter	Yes	Yes	Yes	Yes	
33	USB cable (2 m) (Type-A — Type-C)	Yes *2	Yes *2	-	-	AX-KO7919-200
34	Test sample *1	Yes	Yes	-	1	AX-MX-33
35	Glass fiber sheet	Yes	Yes	-	-	AX-MXA-32-2
36	Disposable aluminum tray	× 100	× 100	× 100	× 100	AX-MXA-30
37	Spoon	Yes	Yes	-	ı	AX-MX-37
38	Tweezers	Yes	Yes	-	-	AX-MX-36
39	Cleaning brushes (large/small)	Yes	Yes	-	-	AX-CLEANING- SET

Yes: Included; -: Not included

^{*1 30} g of sodium tartrate dihydrate

^{*2} UL certified products do not include a USB cable.

3.1. Key Switches and Indicators




No.	Name			
1	Program number			
	Data number (when using data memory)			
2	Measurement mode			
3	Heating pattern			
4	Sample tray temperature indicator			
4	(set value/actual value)			
5	Measurement time (set value/elapsed time)			
6	Measurement accuracy			
7	Target value for sample mass			
/	Moisture change indicator			

No.	Name
8	Level meter
9	Operation indicator
10	USB connection icon
11	Operation icon
12	Stable mass value icon
13	Main display (mass value/moisture content/program ID, etc.)
14	Unit indicator

Example of Displayed Mass





Key Switch Functions and Operations

There are two types of key operations: normal press and long press (press and hold for approx. two seconds).


The regular key operations are normal presses.

Do not long press (press and hold for approx. two seconds) unless necessary.


Key switch		Normal press (press and release immediately)	Long press (for approx. two seconds)
PROGRAM	PROGRAM	Enters the mode for selecting the program number.	Displays the function tests and adjustment modes.
SELECT	SELECT	Enters the mode for changing the measurement conditions.	Enters the mode for changing the internal settings.
	→	Changes the set value.	Continuously changes the set value. (Only for some settings)
PRINT /ENTER	ENTER	Confirms the setting or outputs the displayed value.	Used for GLP output and the data memory function.
START	START	Starts measurement.	Performs preheating.
STOP	STOP	Stops measurement.	
ON:OFF /RESET	RESET	Resets the displayed mass to zero. Turns the display on.	Turns the display off.

4. Requirements for Preparing to Measure (Installation, Initial Configuration, and Measurement)

4.1. Installing the Moisture Analyzer



Step	Description	Diagram
3.	Align the long hole of the breeze break with the protrusion of the main unit.	Breeze break Long hole of breeze break Protrusion of main unit
4.	Align the triangle of the tray holder with the triangle of the main unit.	Triangle of tray holder Tray holder Triangle of the main unit protrusion
5.	Place the sample tray on the sample tray handle, then align the sample tray handle with the notch of the breeze break. CAUTION When using a disposable aluminum tray, make sure to place it on the sample tray.	Sample tray handle Sample tray Notch Place on notch



4.2. Requirements for Ensuring Correct Measurement

4.2.1. Handling Samples

- Perform measurement with an appropriate amount of sample. If the amount of sample is small, the
 accuracy of calculating the moisture content may be adversely affected, which can also affect the
 reproducibility of the measurement results.
- When measuring samples with an expected moisture content of 1% or less (for example, plastic), the moisture content will be unable to be accurately measured if the amount of sample is small, because the change in mass after heating will also be small because the moisture mass is small. Refer to the table below for the estimated sample mass required for measurement.

Expected moisture content	0.5 to 1%	0.1 to 0.5%	Less than 0.1%
Required sample mass	2 g or more	5 g or more	20 g or more

• When measuring materials such as plastic that are prone to static electricity, we recommend that the AD-1683A is used to eliminate static.

Example	Sample	Expected moisture content	Required sample mass	Heating temperature	Termination value
	PBT	0.08%	20 g	160°C	0.005%/min
	ABS	0.43%	10 g	140°C	0.005%/min

- When repeatedly measuring the same sample, it is recommended that you measure the same amount of sample each time.
- For a sample with large granules, crush the sample before measurement to make it easier for the moisture to vaporize.



- Spread the sample out evenly on the tray to ensure that it will be evenly heated.
- A heat drying moisture analyzer is suitable for measuring the moisture content of samples where
 mainly only water will vaporize. Mass changes due to the vaporization or degradation of substances
 other than water will also be measured as moisture.
- For a liquid sample or sample that forms a film on its surface, the use of a glass fiber sheet (AX-MXA-32-2) is recommended. Refer to "4.2.4. Using a Glass Fiber Sheet".

4.2.2. Requirements for the Operation Procedure

- Before performing measurement, press the RESET key and confirm that the displayed mass stabilizes at zero.
- Before pressing the START key to start measurement, confirm that the sample mass is sufficiently stable.
- Configure an appropriate termination value. Use the change in moisture content over time (%/min on the top right of the display) when measurement stops as a guide.
- When repeating measurement, there may be a difference between the first measurement result and
 the subsequent measurement results, due to the heat distribution of the various parts of the moisture
 analyzer. Ignore the first measurement result or perform preheating. (Refer to "4.2.3. How to Use the
 Preheat Function".)
- If you place a sample on the sample tray while the tray is hot, moisture will vaporize before
 measurement, and the moisture content will not be measured accurately. Recommended methods for
 preventing this include alternating between two sample trays when performing consecutive

measurements and waiting about 10 minutes after measurement before performing the next measurement.

- Do not stack sample trays when performing measurement.
- Avoid air conditioner convection and vibrations in the installation location. Otherwise measurement
 errors may occur or the measured value may not stabilize. The MS-74A in particular is susceptible to
 such disturbance, as it is high resolution.
- Accurate temperature control may not be possible if there is only a small difference between the sample tray temperature and the surrounding temperature.
 (Example) When the sample tray temperature is set to around 30°C to 50°C, the product will be more susceptible to the surrounding temperature.
- Use the icon to check the operation of the halogen lamp.
 (e.g.) When the sample tray temperature is set to a low temperature, the halogen lamp will light weaker.

The line gradually lights while the halogen lamp is operating.



4.2.3. How to Use the Preheat Function

- The preheat function raises the temperature around the sample tray before performing moisture content measurement.
- The preheat function is effective for increasing the accuracy of moisture content measurement.
- The preheat function is effective when repeatedly measuring the same sample.
 (Because the heating conditions vary if the starting temperature differs between the first time and the second and subsequent times, the result of measuring the moisture content may also vary.)
- The preheat temperature is automatically determined according to the set measurement conditions.
- Stop preheating at a time of your choice and start measuring the moisture content. If 30 minutes elapse since preheating started, it will automatically stop.

· · · · · · · · · · · · · · · · · · ·	· ·	
Heating pattern*1 setting	Preheat temperature	Time
Standard heating	Temperature ^{*2} setting	
Slow heating	Temperature ^{*2} setting	Maximum 30 min
Step heating	Temperature step 2*2 setting	Waximum 30 min
Rapid heating	Temperature ^{*2} setting	

^{*1} Refer to "6.4.3. Heating Pattern"

^{*2} Refer to "6.4.4. Temperature and Time"

Procedure (preparations before moisture content measurement)

Procedure (preparations before moisture content measurement)				
Step	Description	Operation		
1.	Press and hold the START key.	Press and hold (for approx. 2 seconds)		
2.	With YES selected, press the ENTER key to start preheating.	PRINT		
3.	Preheating starts. The current tray temperature and elapsed preheating time are displayed.	Tray temperature HERL NL Elapsed preheating time		
4.	When the target time has elapsed, press the STOP key or open the heater cover to return to the mass display. The displayed value is reset to zero.	HERL ING STOP STOP PRODE MATTERN SET TEMPS C. D. D. D. D. D. G.		
Remarks	When the preheating time reaches 30 minutes, the heater is automatically turned OFF and Life Life is displayed. Press the STOP key to return to the mass display. The displayed value is reset to zero.	30 minutes since preheating started **PRE 1895 no. 3895 min **PROS MOCK MATERN SET 1895 no. 3895 min **PROS MATERN SET 1895 no. 3895 min **		

4.2.4. Using a Glass Fiber Sheet

 A glass fiber sheet is used for liquid samples, samples that melt when heated, and samples with a surface that is prone to carbonization. Using a glass fiber sheet promotes moisture vaporization and enables faster and more accurate moisture measurement.



100 glass fiber sheets are included in a box (AX-MXA-32-2).
 A box is included with the MS-74A/MX-53A as standard.
 For the MF-53A/ML-53A, glass fiber sheets are available separately.

Example use 1: Liquid sample or sample that melts when heated

Soak the glass fiber sheet with the sample to increase the surface area and space required for moisture vaporization to make it easier for the moisture to vaporize. The glass fiber sheet will also help prevent a hard film from forming on the surface of the sample due to heating.

- Liquid samples with high moisture content

 Example: Milk, yogurt, soy milk, condensed milk, ketchup, resin paint, liquid glue, hand soap, etc.
- Samples that melt when heated and stick to the tray Example: Gum, caramel, honey, etc.

Procedure (preparations before moisture content measurement)

	cedure (preparations before moisture content measurement)				
Step	Description	Operation			
1.	Spread the glass fiber sheet over the sample tray.	Sample tray Glass fiber sheet			
2.	Press the RESET key to reset the displayed value to zero.	PROS MODE MATERN SET TEMP. ON:OFF PROS MODE MATERN SET TEMP. ON:OFF ACCURACY TARGET S.U. 9 G. D.			
3.	Soak the glass fiber sheet with the sample. Or, place the sample on the glass fiber sheet.	Sample			
4.	Press the START key to start heating.	START SEARCE START SERVICE START SERVICE START SERVICE START START SERVICE START START SERVICE START START START SERVICE START START SERVICE START S			

Example use 2: Sample with a surface prone to carbonization

Cover the sample with the glass fiber sheet to reduce the sample surface carbonization due to heating.

Preventing sample carbonization enables stable measurement of the moisture content.

Samples including a lot of sugar, protein, or oil
 Example: Honey, soy bean powder, tea leaves, cookies, etc.

• Samples with a black surface that are prone to burning Example: Coffee, peanuts, etc.

Procedure (preparations before heating)

Step	Description	Operation
1.	Spread the glass fiber sheet over the sample tray.	Sample tray Glass fiber sheet
2.	Press the RESET key to reset the displayed value to zero.	PROD MODE PATTERN SET THANK ACCURACY TARGET S.G., G.
		FROO MODE MATIEM SET HIMP. 1 Std
3.	Remove the glass fiber sheet.	
		FROO MODE MATHRM SET HAMP. 1 5 b d
4.	Place the sample on the sample tray.	Sample Bad Good Make the sample
		PROOF MODE PATIENT SET TIME. 1 5 b d

Step	Description	Operation
5.	Cover the top of the sample with the glass fiber sheet removed in step 3.	
		PROD MODE PATTERN SET HAMP. ACCURACY TARGET
		FROOD MODE PATIENT SET TEMP. 1 5 b d
6.	Press the START key to start heating.	START
		™ SEARE

5. Measurement

Measure the moisture content.

To change the measurement conditions, refer to "6.4. Detailed Description of Measurement Conditions".

5.1. Procedure for Measuring the Moisture Content

Step	Description	Operation
1.	Turn the power of the main unit ON and display the mass.	PRODUIEM MODE PATIENT SET TIME, SET
2.	Place the sample tray on the sample tray handle and load them on the tray holder. CAUTION Place the sample tray handle in the notch of the breeze break.	Sample tray handle Sample tray Notch of breeze break Preparing the tray
3.	Close the heater cover.	Close
4.	When the stable mass value icon lights and the displayed value stabilizes, press the RESET key to reset the displayed mass to zero. (Avoid disturbance such as vibrations during measurement.) If the displayed mass deviates from zero, press the RESET key to reset it to zero.	PRINT /ENTER PROD MORE MATTERN SET TEMP. PRINT /ENTER PRINT /ENTER ACCURACY TARGET S. 0 g
5.	Open the heater cover and load an appropriate amount of sample, using the level meter as a guide. CAUTION At least 0.1 g of sample is required. Make the sample as flat as possible.	When there is 0.1 g or more of the sample, the icon lights and measurement can be performed. Bad Good

Step	Description	Operation
Rem arks	By pressing the	FROG MODE MITTEN SET TEMP. S. G.
Rem arks	You can press the ENTER key to output (print) the current mass value. Example computer output (RsCom of WinCT) Standard A&D format (default setting) ST,+0005.030_g <term> : Space (ASCII 20h) <term>: Terminator (CR LF or CR) CR : Carriage return (ASCII 0Dh) LF : Line feed (ASCII 0Ah)</term></term>	PRINT /ENTERN
6.	Close the heater cover, wait until the mass value stabilizes, then press the START key. The measured value changes according to the vaporization of the moisture in the sample.	START Measurement time Change in moisture content Change in moisture content Measured Value Measured Value

Step	Description	Operation	
Rem arks	You can press a key during measurement to temporarily select a different measurement basis.	MITTEN TIME TAKE TAKE TAKE TO 19 1/9 1/min 0.19 1/min 0	
	CAUTION	Display	\exists
	The data output also changes according to the measurement basis. Do not switch the unit while measurement data is being output.	% Moisture content w (standard before drying))
		Moisture Moisture content (standard after drying)	
		% RATIO Solids	
		% RATIO Ratio	
		g Grams	
7.	When the termination value is met (either the moisture content going below a certain value or heating continuing for a certain time), a buzzer sounds and measurement stops.	End 105% 8.6 min 3.2 7% MOIST	
8.	You can perform the following operations while the result is displayed. The selected text flashes.		
	ENTER key The data is output (printed).		
	keys Switch the displayed result between percentage and grams.		
	SELECT key, RESET key The product returns to the mass display (step 1).		
	Example computer output (RsCom of WinCT)		
	Standard A&D format ST,+00003.27% <term> : Space (ASCII 20h)</term>		
	<term> : Terminator (CR LF or CR) CR : Carriage return (ASCII 0Dh) LF : Line feed (ASCII 0Ah)</term>		

Step	Description	Operation
9.	Open the heater cover, raise the sample tray with the sample tray handle, then take out the sample.	
	ADVICE ■ The sample tray can be washed and reused.	Take out the sample

6. Measurement Conditions

You can save measurement conditions of your choice to program numbers 1 to 200.

By selecting a program number (1 to 200), you can recall the measurement conditions saved to that number. To perform moisture content measurement with the recalled measurement conditions, refer to "5. Measurement" to start measurement.

To change and save the measurement conditions, refer to "6.4. Detailed Description of Measurement Conditions".

Example measurement conditions are saved to program numbers 201 and beyond. To use the example measurement conditions, refer to "6.2.2. How to Use Example Measurement Conditions".

6.1. How to Select a Program Number

Follow the procedure below to select the program number.

By selecting a program number, you can recall the measurement conditions saved to that number.

To save new measurement conditions, select the program number to save to, then change and save the measurement conditions (refer to "6.4. Detailed Description of Measurement Conditions").

Step	Description	Operation						
1.	Press the PROGRAM key with the mass displayed to display the screen for selecting the measurement conditions.	PROGRAM PRO						
2.	The program number flashes. An overview of the measurement conditions is displayed. \begin{align*} \psi & keys \\	PRINT / STOP						
3.	The product returns to the mass display.	FROO MODE PATIEN SET HIME. 105 % S.0 9 0.000 g						

6.2. Example Measurement Conditions

The product contains example measurement conditions for various types of samples.

When measuring a sample for the first time, you can copy example measurement conditions to a program number from 1 to 200.

You can also change the measurement conditions after copying them.

6.2.1. List of Example Measurement Conditions and Actual Measurement Results

Household Items

Program		Program	Heating	Termination	Sample	Maasuramant	Moisture content			
number	Sample	Sample Program Heating Termination Sample Measurer temperature value*1 mass time	time	Average value	Reproducibility	CV value	Remarks			
201	Cigarette	TOBACCO	100°C	0.10%/min	0.9 to 1.1 g	6.5 min	10.58	0.339	3.20	Take apart the sample and measure only the tobacco. There will be a strong odor during heating.
202	Dog food	DOGFOOD	160°C	0.10%/min	0.9 to 1.1 g	9.2 min	8.68	0.059	0.68	Pulverize the sample with a blender before measuring. There will be a strong odor during heating.
203	Toothpaste	ТООТН Р	180°C	0.05%/min	0.9 to 1.1 g	8.8 min	51.70	0.046	0.09	Spread the sample over a glass fiber sheet before measuring.
204	Starch glue	STARCHG	200°C	0.05%/min	4.5 to 5.5 g	16.0 min	77.57	0.193	0.25	Spread the sample out evenly before measuring.
205	Laundry starch (liquid)	LSTARCH	200°C	0.05%/min	0.9 to 1.1 g	5.0 min	93.06	0.118	0.13	Spread the sample over a glass fiber sheet before measuring.
206	Wood glue	BOND	200°C	0.05%/min	0.9 to 1.1 g	9.7 min	40.75	0.349	0.86	Spread the sample over a glass fiber sheet before measuring.
207	Hand soap	HNDSOAP	200°C	0.05%/min	0.9 to 1.1 g	7.6 min	91.57	0.077	0.08	Spread the sample over a glass fiber sheet before measuring.

Drogram		Dragram	Heating	Tarmination	Cample	Magauramant	М	Moisture content		
Program number	Sample	Program ID	Heating temperature	. 44	mass	Measurement time	Average value	Reproducibility	CV value	Remarks
208	Lipstick	LIPSTK	100°C	0.01%/min	0.9 to 1.1 g	3.6 min	0.64	0.063	9.86	Spread the sample out directly on the sample tray before measuring.
209	Foundation (liquid)	FNDTN	160°C	0.05%/min	0.9 to 1.1 g	12.2 min	79.69	0.543	0.68	Spread the sample over a glass fiber sheet before measuring.
210	Dry chips (chips of Yezo pine)	DRYCHIP	200°C	0.05%/min	0.9 to 1.1 g	6.6 min	13.55	0.386	2.85	Cut the sample into small strips before measuring.
211	Silica sand	SILSAND	200°C	0.01%/min	9.0 to 11.0 g	4.1 min	0.30	0.022	7.35	
212	Cement (powder)	CEMENT	200°C	0.01%/min	9.0 to 11.0 g	4.1 min	0.68	0.018	2.63	
213	Water-based putty (paste)	PUTTY	160°C	0.05%/min	0.9 to 1.1 g	7.5 min	19.48	0.380	1.95	Use a disposable aluminum tray. Spread the sample out in a thin layer before measuring.
214	Synthetic resin paint (water-based acrylic paint, liquid)	RESINPT	200°C	0.05%/min	0.9 to 1.1 g	16.2 min	54.13	0.254	0.47	Use a disposable aluminum tray. Soak in filter paper before measuring.

^{*1} For some models, the setting value in the table may be lower than the lower limit value. In that case, the setting value will be set to the lower limit value.

Household Items

Program		Drogram	Heating	Tarmination	Sample	Measurement-	Moisture content			
number	Sample	Program ID	temperature	. +4	mass	time	Average	Reproducibility	CV	Remarks
Hamber		10	temperature	value	111000		value	reproducibility	value	,
215	Copy paper	XER	200°C	0.05%/min	0.9 to 1.1 g	3.2 min	6.58	0.128	1.95	Cut the sample into small strips before
213	Copy paper	PAP	200 C	0.03 /0/111111	0.910 1.19	3.2 111111	0.56	0.120	1.55	measuring.
		CARD								Cut the sample into small strips before
216	Cardboard	BD	100°C	0.05%/min	0.9 to 1.1 g	5.2 min	8.20	0.028	0.34	measuring.
										Measure after preheating.
047	Plastic film	5 50 14	100°C	0.02%/min	0.9 to 1.1 g	2.4 min	0.43	0.044	10.32	Cut the sample into small strips before
217		P FILM			0.9 to 1.1 g					measuring.

^{*1} For some models, the setting value in the table may be lower than the lower limit value. In that case, the setting value will be set to the lower limit value.

Food A (grains, beans, seafood, condiments, seasonings, additives)

Program		Program	Heating	Termination value ^{*1}	Sample l mass	Measurement time	Moisture content			
number			temperature				Average value	Reproducibility	CV value	Remarks
218	Corn grits	CORNGTZ	160°C	0.05%/min	4.5 to 5.5 g	14.6 min	13.52	0.017	0.13	
219	Corn starch	CORNST	200°C	0.05%/min	4.5 to 5.5 g	8.0 min	12.86	0.030	0.23	
220	Potato starch	STARCH	200°C	0.05%/min	4.5 to 5.5 g	8.4 min	17.06	0.089	0.52	
221	Buckwheat flour	SOBAFLR	180°C	0.05%/min	4.5 to 5.5 g	12.1 min	13.26	0.081	0.61	
222	Cake flour	CAKEFLR	200°C	0.05%/min	4.5 to 5.5 g	8.1 min	11.71	0.061	0.52	
223	Rice flour	RICEFLR	200°C	0.05%/min	4.5 to 5.5 g	10.5 min	12.53	0.028	0.22	
224	Rolled oats	ROLOATS	200°C	0.05%/min	4.5 to 5.5 g	14.1 min	12.45	0.093	0.75	
225	Pregelatinized oats (dried powder)	PREOATS	160°C	0.10%/min	0.9 to 1.1 g	19.7 min	11.80	0.352	2.98	
226	White rice	RICE	200°C	0.10%/min	4.5 to 5.5 g	14.3 min	15.88	0.198	1.25	Pulverize the sample with a blender before measuring.
227	Pre-washed rice	PRERICE	200°C	0.10%/min	0.9 to 1.1 g	9.4 min	16.08	0.214	1.33	
228	Packaged white rice	PACKRCE	200°C	0.05%/min	1.8 to 2.2 g	19.4 min	64.94	1.235	1.90	
229	Soy flour	SOY FLR	160°C	0.05%/min	1.8 to 2.2 g	4.6 min	3.89	0.094	2.41	
230	Cashew nuts	CASNUTS	140°C	0.05%/min	4.5 to 5.5 g	7.4 min	1.72	0.065	3.77	Pulverize the sample with a blender before measuring.
231	Buttered peanuts	BTPEANT	160°C	0.05%/min	4.5 to 5.5 g	9.1 min	2.85	0.027	0.95	Pulverize the sample with a blender before measuring.
232	Coffee beans (powder)	C BEAN	140°C	0.05%/min	2.7 to 3.3 g	7.9 min	2.75	0.038	1.38	Cover the sample with a glass fiber sheet before measuring.
233	Dried squid	DRD SQD	200°C	0.05%/min	1.8 to 2.2 g	24.0 min	20.42	1.496	7.33	Cut the sample into small strips before measuring.

^{*1} For some models, the setting value in the table may be lower than the lower limit value. In that case, the setting value will be set to the lower limit value.

Food A (grains, beans, seafood, condiments, seasonings, additives)

	(grains, beans, searood, cond						Moisture content			
Program number	Sample	Program ID	Heating temperature		Sample	Measurement time	Average value	Reproducibility	CV value	Remarks
234	Rehydrated squid	RHD SQD	160°C	0.05%/min	1.8 to 2.2 g	29.3 min	16.40	0.537	3.27	Cut the sample into small strips before measuring.
235	Dried sardine	DRDSRDN	200°C	0.05%/min	1.8 to 2.2 g	11.0 min	17.02	0.246	1.45	Pulverize the sample with a blender before measuring.
236	Dried whitebait	DRD WBT	200°C	0.05%/min	4.5 to 5.5 g	16.5 min	69.70	0.733	1.05	
237	Raw salmon	SALMON	200°C	0.05%/min	2.7 to 3.3 g	27.8 min	58.39	1.315	2.25	Use a disposable aluminum tray.
238	Dried bonito shavings	DRDBNTO	120°C	0.05%/min	0.9 to 1.1 g	6.1 min	14.30	0.765	5.35	
239	Fish sausage	FIS SG	200°C	0.05%/min	1.8 to 2.2 g	21.7 min	77.60	0.300	0.39	Cut the sample into small strips before measuring.
240	Freeze dried scallions	FD SCAL	100°C	0.05%/min	0.9 to 1.1 g	5.4 min	2.41	0.102	4.23	
241	Dried mushroom	DRDMSHM	140°C	0.05%/min	0.9 to 1.1 g	7 min	7.71	0.203	2.63	Cut the sample into small strips before measuring.
242	Dried sweet potato	DRDSWPT	140°C	0.05%/min	0.9 to 1.1 g	32.2 min	29.44	0.891	3.03	Cut the sample into 3 mm slices and place the slices on a glass fiber sheet before measuring.
243	White radish	RADISH	200°C	0.05%/min	1.8 to 2.2 g	18.9 min	94.66	0.073	0.08	Pulverize the sample with a blender before measuring.
244	Cabbage	CABBAGE	200°C	0.05%/min	0.9 to 1.1 g	16.1 min	92.86	0.089	0.10	Pulverize the sample with a blender before measuring.
245	Pumpkin	PUMPKIN	200°C	0.05%/min	1.8 to 2.2 g	22.6 min	84.98	0.283	0.33	Pulverize the sample with a blender before measuring.
246	Bell pepper	BLPEPPR	200°C	0.05%/min	1.8 to 2.2 g	18.8 min	93.80	0.094	0.10	Pulverize the sample with a blender before measuring.
247	Dried seaweed	SEAWEED	200°C	0.05%/min	0.9 to 1.1 g	7.8 min	4.02	0.195	4.85	Cut the sample into small strips before measuring.
248	Sugar crystals (powder)	SUGCRYS	140°C	0.01%/min	4.5 to 5.5 g	3.3 min	0.17	0.018	10.87	
249	Brown sugar (powder)	BRN SUG	120°C	0.01%/min	4.5 to 5.5 g	6.0 min	0.69	0.071	10.22	

Drogram		Dragram	Heating	Tarmination	Cample	Magauramant	M	oisture content		
Program number	Sample	Program ID	Heating temperature	. 44	mass	Measurement time	Average	Reproducibility	CV value	Remarks
							value		value	
250	Salt	SALT	200°C	15 min	9.0 to 11.0 g	15.0 min	0.06	0.003	5.97	
251	Seasoning salt	S SALT	120°C	15 min	9.0 to 11.0 g	15.0 min	0.07	0.010	12.79	
252	Flavor seasoning	FLVSSN	140°C	0.05%/min	4.5 to 5.5 g	4.4 min	0.88	0.034	3.88	
253	Granulated stock	GRANULE	120°C	0.05%/min	4.5 to 5.5 g	13.6 min	2.77	0.136	4.91	
254	Tomato ketchup	KTCHP	160°C	0.05%/min	0.9 to 1.1 q	18.1 min	68.67	0.533	0.78	Spread the sample over filter paper
234	Tomato ketchup	KICHE	100 C	0.05 /0/111111	0.9 to 1.1 g	10.1 111111	00.07	0.555	0.70	before measuring.
255	Mayannaiaa (yalk tyna)	MAYO	180°C	0.05%/min	0.9 to 1.1 g	6.6 min	18.92	0.535	2.83	Spread the sample over a glass fiber
200	Mayonnaise (yolk type)	IVIATO	100 C	0.05%/MIII	0.9 to 1.1 g	o.o min	10.92	0.555		sheet before measuring.

^{*1} For some models, the setting value in the table may be lower than the lower limit value. In that case, the setting value will be set to the lower limit value.

Food A (grains, beans, seafood, condiments, seasonings, additives)

Drogram		Dragram	Heating	Tarmination	Cample	Magauramant		oisture content		
Program number	Sample	Program ID	Heating temperature	. +4	mass	Measurement time	Average value	Reproducibility	CV value	Remarks
256	Pepper (roughly ground)	PEPPER	200°C	0.05%/min	4.5 to 5.5 g	20.1 min	14.20	0.134	0.94	
257	Curry powder	CURRYPW	180°C	0.05%/min	0.9 to 1.1 g	9 min	9.58	0.163	1.70	
258	Japanese pepper	SANSHO	120°C	0.05%/min	1.8 to 2.2 g	17.6 min	9.45	0.397	4.20	
259	Chili pepper	CHILI	120°C	0.05%/min	2.7 to 3.3 g	12.8 min	5.26	0.061	1.16	
260	Shichimi seasoning	SC CHIL	120°C	0.05%/min	2.7 to 3.3 g	12.0 min	4.35	0.120	2.76	
261	Wasabi paste	PAS WAS	180°C	0.05%/min	0.9 to 1.1 g	16.4 min	39.58	0.402	1.02	Use a disposable aluminum tray. Crush the sample with a glass fiber sheet before measuring.
262	Wasabi powder	POW WAS	140°C	0.05%/min	3.6 to 4.4 g	8.8 min	3.52	0.050	1.42	
263	Mustard paste (paste with grains)	MUSTARD	200°C	0.05%/min	0.9 to 1.1 g	20.1 min	47.51	0.422	0.89	Use a disposable aluminum tray. Cover the sample with a glass fiber sheet before measuring.
264	Mustard powder	POWMSTD	140°C	0.05%/min	3.6 to 4.4 g	7.5 min	4.09	0.030	0.73	
265	Ginger paste	GINGER	200°C	0.05%/min	0.9 to 1.1 g	13.8 min	87.01	0.366	0.42	Use a disposable aluminum tray. Cover the sample with a glass fiber sheet before measuring.
266	Citric acid	CITRIC	100°C	0.10%/min	4.5 to 5.5 g	7.2 min	4.54	0.210	4.63	
267	Anhydrous glucose	ANHYGLU	140°C	0.05%/min	4.5 to 5.5 g	1.2 min	0.21	0.022	10.48	

^{*1} For some models, the setting value in the table may be lower than the lower limit value. In that case, the setting value will be set to the lower limit value.

Food B (processed foods, dairy products, confectionery, other)

Program		Program	Heating	Tormination	Sample	Measurement	M	oisture content		
number	Sample		temperature	. 44	mass	time	Average	Reproducibility	CV	Remarks
Humber		טו	temperature	value	111055	uiiio	value	Reproducibility	value	
268	Bread	BREAD	160°C	0.05%/min	0.9 to 1.1 g	10.7 min	41.97	0.611	1.46	Cut the sample into small strips before
200	Bicad	BINEAD	100 0	0.0070/111111	0.0 10 1.19	10.7 111111	41.57	0.011	1.40	measuring.
269	Breadcrumbs	BRDCRMB	200°C	0.05%/min	0.9 to 1.1 g	6.9 min	11.52	0.087	0.76	
270	Dried soup	DRYSOUP	120°C	0.05%/min	0.9 to 1.1 g	8.4 min	3.29	0.048	1.46	Corn cream soup. Remove the kernels
270	Dried Soup	DRISOUP	120 C	0.0570/111111	0.910 1.19	0.4 111111	3.29	0.046		before measuring.

^{*1} For some models, the setting value in the table may be lower than the lower limit value. In that case, the setting value will be set to the lower limit value.

Food B (processed foods, dairy products, confectionery, other)

Program		Program	Heating	Termination	Sample	Measurement		oisture content		
Program number	Sample		temperature	. 44	mass	time	Average value	Reproducibility	CV value	Remarks
	Instant bean paste soup	BP SOUP	200°C	0.05%/min	0.9 to 1.1 g	18.3 min	65.37	0.364	0.56	Use a disposable aluminum tray.
271										Place on filter paper before
										measuring.
272	Instant noodles	INSTNDL	180°C	0.05%/min	1.8 to 2.2 g	8.2 min	1.82	0.051	2.81	Crush the sample into small pieces
ZIZ										before measuring.
273	Croutons	SIPPET	200°C	0.05%/min	1.8 to 2.2 g	8.5 min	8.02	0.158	1.97	Crush the sample into small pieces
210										before measuring.
274	Breakfast cereal (brown rice)	CEREAL	180°C	0.05%/min	1.8 to 2.2 g	7.2 min	2.33	0.050	2.14	Crush the sample into small pieces
214										before measuring.
275	Dried spaghetti	PASTA	200°C	0.05%/min	1.8 to 2.2 g	31.3 min	11.50	0.203	1.77	Crush the sample into small pieces
210										before measuring.
276	Dried udon noodles	DRYUDON	200°C	0.05%/min	4.5 to 5.5 g	18 min	14.04	0.445	3.17	Cut the sample into 1 cm slices before
210										measuring.
277	Boiled udon noodles	UDON	200°C	0.05%/min	2.7 to 3.3 g	23.3 min	67.37	0.257	0.38	
278	Dried vermicelli	B VERM	200°C	0.05%/min	1.8 to 2.2 g	22.3 min	11.80	0.132	1.12	Cut the sample into 1 cm slices before

D		D	114	T	0	N 4 4	N	loisture content		
Program number	Sample	Program ID	Heating temperature	. +4	mass	Measurement time	Average	Reproducibility	CV value	Remarks
										measuring.
279	Dried seaweed	SEAWEED	200°C	0.05%/min	0.9 to 1.1 g	11.51 min	8.90	0.250	2.81	Pulverize the sample with a blender before measuring.
280	Sliced wood ear mushroom	WOODEAR	180°C	0.05%/min	1.8 to 2.2 g	25.7 min	14.39	0.205	1.42	Pulverize the sample with a blender before measuring.
281	Beef jerky	BFJERKY	180°C	0.05%/min	1.8 to 2.2 g	29.5 min	20.10	0.974	4.85	Cut the sample into small strips before measuring.
282	Rice cracker	R CRACK	200°C	0.05%/min	4.5 to 5.5 g	10.0 min	5.64	0.128	2.27	Crush the sample into small pieces in a mortar before measuring.
283	Cookie	COOKIE	160°C	0.05%/min	4.5 to 5.5 g	6.3 min	2.11	0.066	3.13	Lightly crush the sample before measuring.
284	Langue de chat cookie	LNGCHAT	160°C	0.05%/min	1.8 to 2.2 g	6.1 min	2.45	0.069	2.82	Lightly crush the sample before measuring.
285	Frozen pie dough	PIE DGH	200°C	0.05%/min	1.8 to 2.2 g	12.5 min	30.65	0.209	0.68	Cut the sample into small slices with scissors before measuring.
286	Sliced banana chips	Banana chips	160°C	0.05%/min	1.8 to 2.2 g	7.9 min	1.98	0.259	13.03	Crush the sample into small pieces in a mortar before measuring.
287	Potato chips	P CHIPS	160°C	0.05%/min	4.5 to 5.5 g	8.3 min	2.19	0.060	2.74	Lightly crush the sample before measuring.
288	Shrimp snacks	S SNACK	160°C	0.05%/min	0.9 to 1.1 g	4.5 min	2.55	0.146	5.73	Lightly crush the sample before measuring.
289	Noodle snacks	N SNACK	160°C	0.05%/min	4.5 to 5.5 g	8.4 min	1.54	0.040	2.60	
290	Gummy	GUMMY	120°C	0.05%/min	2.7 to 3.3 g	29.7 min	3.40	0.235	6.92	Use a disposable aluminum tray.
291	Strawberry jam	JAM	180°C	0.05%/min	0.9 to 1.1 g	15.7 min	59.84	0.780	1.30	Spread the sample over filter paper before measuring.
292	Honey at 120°C	HONEY 1	120°C	0.05%/min	0.9 to 1.1 g	19.5 min	17.05	0.338	1.98	Spread the sample over filter paper before measuring.
293	Honey at 140°C	HONEY 2	140°C	0.05%/min	0.9 to 1.1 g	14.1 min	18.61	0.326	1.75	Spread the sample over filter paper before measuring.

^{*1} For some models, the setting value in the table may be lower than the lower limit value. In that case, the setting value will be set to the lower limit value.

Food B (processed foods, dairy products, confectionery, other)

	(processed resue, dairy proc			_	Cample	Magauramant	I	loisture content		
Program number	Sample	Program ID	Heating temperature		mass	Measurement time	Average	Reproducibility	CV value	Remarks
294	Honey at 160°C	HONEY 3	160°C	0.05%/min	0.9 to 1.1 g	24.6 min	21.78	1.578	7.25	Spread the sample over filter paper before measuring.
295	Red bean paste (chunky)	ANKO	180°C	0.05%/min	0.9 to 1.1 g	11.6 min	33.56	0.194	0.58	Use a disposable aluminum tray. Cover the sample with a glass fiber sheet before measuring.
296	Milk	MILK	160°C	0.05%/min	0.9 to 1.1 g	7.2 min	88.49	0.335	0.38	Use a disposable aluminum tray. Cover the sample with a glass fiber sheet before measuring.
297	Solid salted butter	BUTTER	200°C	0.05%/min	0.9 to 1.1 g	3.13 min	15.00	0.542	3.61	Spread the sample over a glass fiber sheet before measuring.
298	Granulated cheese	GCHEESE	200°C	0.05%/min	0.9 to 1.1 g	10 min	13.75	0.110	0.80	
299	Skim milk	S MILK	140°C	0.10%/min	1.8 to 2.2 g	16.7 min	6.49	0.255	3.93	
300	Infant formula	MP MILK	140°C	0.05%/min	1.8 to 2.2 g	5.7 min	3.07	0.145	0.80	
301	Hard yogurt	YOGURT	200°C	0.05%/min	0.9 to 1.1 g	13 min	85.20	0.334	0.39	Spread the sample over a glass fiber sheet before measuring.
302	Coffee creamer	MSUBST	180°C	0.05%/min	0.9 to 1.1 g	6.9 min	88.11	0.294	0.33	Use a disposable aluminum tray. Cover the sample with a glass fiber sheet before measuring.
303	Condensed milk	C MILK	160°C	0.05%/min	0.9 to 1.1 g	16 min	28.74	0.311	1.08	Use a disposable aluminum tray. Place on filter paper before measuring.
304	Fat spread	FATSPRD	200°C	0.05%/min	0.9 to 1.1 g	3.25 min	31.26	0.486	1.55	Spread the sample over a glass fiber sheet before measuring.
305	Soy milk	SOYMILK	140°C	0.05%/min	0.9 to 1.1 g	7.5 min	96.65	0.648	0.67	Use a disposable aluminum tray. Soak in filter paper before measuring.
306	Green tea leaves	GRN TEA	120°C	0.05%/min	4.5 to 5.5 g	10.4 min	2.03	0.035	1.72	Pulverize the sample with a blender before measuring.

Drogram		Drogram	Heating	Tormination	Cample	Magauramant	M	loisture content		
Program number	Sample	Program ID	Heating temperature	value ^{*1}	mass	Measurement time	Average	Reproducibility	CV	Remarks
Hullibel		טו	temperature	value	111055		value	Reproducibility	value	
307	Instant coffee powder	COFFEE	120°C	0.05%/min	3.6 to 4.4 g	11.2 min	4.20	0.182	4.33	Cover the sample with a glass fiber
307	instant conee powder	COLLE	120 0	0.0570/111111	5.0 to 4.4 g	11.2 111111	4.20	0.102		sheet before measuring.
										Use a disposable aluminum tray.
308	Reconstituted orange juice	O JUICE	160°C	0.05%/min	0.9 to 1.1 g	10.3 min	89.68	0.380	0.42	Cover the sample with a glass fiber
										sheet before measuring.
309	Powdered sports drink	P BEVER	120°C	0.01%/min	4.5 to 5.5 g	4.3 min	0.23	0.024	10.53	
										Use a disposable aluminum tray.
310	Jellied sports drink	G BEVER	180°C	0.05%/min	0.9 to 1.1 g	17.1 min	75.49	0.431	0.57	Place on filter paper before
										measuring.
311	Agar powder	AGARPOW	200°C	0.05%/min	4.5 to 5.5 g	7.5 min	15.95	0.066	0.41	
312	Gelatin powder	GELATIN	200°C	0.05%/min	4.5 to 5.5 g	9.4 min	12.46	0.030	0.24	

^{*1} For some models, the setting value in the table may be lower than the lower limit value. In that case, the setting value will be set to the lower limit value.

Chemicals

Drogram		Drogram	Hooting	Tormination	Comple	Magauramant	Me	oisture content		
Program number	Sample	Program ID	Heating temperature	. +4	mass	Measurement time	Average value	Reproducibility	CV value	Remarks
313	Skin care cream	SKINCRM	180°C	0.05%/min	0.9 to 1.1 g	19.8 min	75.08	0.514	0.68	Place the squashed sample between a glass fiber sheet folded into two before measuring.
314	Sodium tartrate	TARTNA	160°C	0.05%/min	4.5 to 5.5 g	8 min	15.71	0.007	0.04	
315	Cellulose	CELLOSE	200°C	0.05%/min	4.5 to 5.5 g	4.3 min	4.00	0.073	1.83	
316	Calcium stearate	STECA	180°C	0.10%/min	4.5 to 5.5 g	7.6 min	2.90	0.030	1.03	There will be a strong odor during heating.
317	Zinc oxide	ZN OX	200°C	0.01%/min	4.5 to 5.5 g	4.8 min	0.14	0.010	7.04	
318	Aluminum oxide	ALUM OX	200°C	0.01%/min	4.5 to 5.5 g	6.5 min	0.25	0.006	2.38	
319	Magnesium oxide	MG OX	200°C	0.01%/min	1.8 to 2.2 g	3 min	0.44	0.020	4.40	
320	Talc	TALC	160°C	0.01%/min	4.5 to 5.5 g	5.1 min	0.18	0.011	6.15	Measure after preheating.
321	Calcium carbonate	CACO3	200°C	0.01%/min	4.5 to 5.5 g	5.8 min	0.12	0.004	3.42	

^{*1} For some models, the setting value in the table may be lower than the lower limit value. In that case, the setting value will be set to the lower limit value.

Industrial Products

Drogram		Drogram	Heating	Termination	Sample	Magauramant	M	oisture content		
Program number	Sample	Program ID	Heating temperature	. *4	mass	Measurement time	Average	Reproducibility	CV value	Remarks
322	Powdered charcoal	CHARCL	200°C	0.05%/min	0.9 to 1.1 g	2.3 min	6.81	0.777	11.40	Lightly crush the sample before measuring.
323	Activated carbon granules for deodorization	ACTCHAR	120°C	0.05%/min	4.5 to 5.5 g	2.4 min	2.65	0.070	2.64	Cover the sample with a glass fiber sheet before measuring.
324	Red soil granules	REDSOIL	200°C	0.05%/min	2.7 to 3.3 g	10.1 min	27.45	0.475	1.73	
325	Silica gel particles	SIL PRT	200°C	0.05%/min	4.5 to 5.5 g	6.4 min	19.40	0.032	0.16	Leave the sample for one day at 23°C room temperature before measuring.
326	Black printer toner	P TONER	100°C	0.10%/min	4.5 to 5.5 g	1.6 min	0.30	0.013	4.36	

^{*1} For some models, the setting value in the table may be lower than the lower limit value. In that case, the setting value will be set to the lower limit value.

Plastics

D=======		D	I I a a tim a	T	Camania	N. 4	М	oisture content		
Program number	Sample	Program ID	Heating temperature	Termination value ^{*1}	Sample mass	time	Average value	oisture content Reproducibility	CV value	Remarks
										When measuring a 0.5 g sample
										heated to 230°C with the Karl Fischer
327	PC pellets	PC	130°C	0.001%/min	24.0 to 25.0 g	15 min	0.093	0.002	2.15	method three times and taking the
321	r o peliets	FC	130 C	0.001/0/111111	24.0 to 25.0 g	13 111111	0.093	0.002	2.13	average: 0.077% moisture content
										and 0.0021% reproducibility with a
										measurement time of 30 minutes
										When measuring a 2 g sample heated
										to 200°C with the Karl Fischer method
328	POM pellets	POM	130°C	0.001%/min	24.0 to 25.0 g	15.6 min	0.101	0.0009	0.89	three times and taking the average:
320	r Ow peliets	FOIVI	130 C	0.001/0/111111	24.0 to 25.0 g	13.0 111111	0.101	0.0009	0.09	0.087% moisture content and
										0.0022% reproducibility with a
										measurement time of 30 minutes
										When measuring a 3 g sample heated
										to 230°C with the Karl Fischer method
329	PET pellets	PET	160°C	0.001%/min	24.0 to 25.0 g	9.0 min	0.045	0.0008	1.78	three times and taking the average:
329	(polyethylene terephthalate)	1 -	100 C	0.00170/11111	24.0 to 25.0 g	9.0 111111	0.043	0.0000	1.70	0.027% moisture content and
										0.0025% reproducibility with a
										measurement time of 30 minutes
										When measuring a 0.1 g sample
										heated to 200°C with the Karl Fischer
330	ARS resin pellets	ARS	130°C	0.001%/min	24 0 to 25 0 a	21 0 min	0.203	0.0027	1.33	method three times and taking the
330	Abo resiri periets	esin pellets ABS	ABS 130°C	0.001%/min 2	in 24.0 to 25.0 g	5.0g 21.0 min	0.203 0.0027	1.55	average: 0.192% moisture content	
									and 0.0097% reproducibility with a	
										measurement time of 30 minutes

^{*1} For some models, the setting value in the table may be lower than the lower limit value. In that case, the setting value will be set to the lower limit value.

Electrical Components

Dragram		Drogram	Heating	Termination	Cample	Measurement	Мо	oisture content		
Program number	Sample	Program ID	Heating temperature	. *4	mass	time	Average value	Reproducibility	CV value	Remarks
331	CPU (100 pin plastic QFP, 14 × 20 mm)	CPU	120°C	0.05%/min	9.0 to 11.0 g	1.7 min	0.06	0.006	8.59	Leave the sample for two days in a thermostatic tank at 80% RH and 30°C room temperature before measuring.

^{*1} For some models, the setting value in the table may be lower than the lower limit value. In that case, the setting value will be set to the lower limit value.

Rubber

Drogr		Drogram	Hooting	Tormination	Sample	Measurement	M	oisture content		
Progra	Sample	Program ID	Heating temperature	. *4	mass	time	Average value	Reproducibility	CV value	Remarks
332	Pulverized tire	TIRE	200°C	0.10%/min	4.5 to 5.5 g	4.3 min	22.30	0.080	0.36	Pulverize the sample before measuring.

^{*1} For some models, the setting value in the table may be lower than the lower limit value. In that case, the setting value will be set to the lower limit value.

Sewage

Drogram		Drogram	Heating	Termination	Sample	Measurement	М	oisture content		
Program	Sample	Program ID	Heating temperature	. +4	mass	time	Average value	Reproducibility	CV value	Remarks
333	Liquid sewage	SEWAGE	140°C	0.10%/min	0.9 to 1.1 g	5.7 min	99.14	0.233	0.24	Use a glass fiber sheet. There will be a strong odor during heating.
334	Sewage paste	SEWAGEP	200°C	0.10%/min	4.5 to 5.5 g	16.3 min	86.64	0.560	0.65	There will be a strong odor during heating.

^{*1} For some models, the setting value in the table may be lower than the lower limit value. In that case, the setting value will be set to the lower limit value.


6.2.2. How to Use Example Measurement Conditions

Step	Description	Operation
1.	Refer to "6.1. How to Select a Program Number" to select the program number to change the measurement conditions of.	PROG MODE NATION SET TEMP. 105 c
2.	Press the PROGRAM key with the mass displayed to display the screen for selecting the measurement conditions.	PROGRAM PRO
3.	The program number flashes. An overview of the measurement conditions is displayed. Press the	POOL MODE MITTEN SET TEMP. PO
4.	Press the ENTER key.	PRINT /ENTER
5.	The product returns to the mass display. The example measurement conditions selected in step 4 are copied to the program number selected in step 1. You can change the measurement conditions after copying them. (Refer to "6.4. Detailed Description of Measurement Conditions".)	PROS NOOL PATIEN SIT TIMP. (Lu 5 t - 1000 c

6.3. Overview of Measurement Conditions

6.3.1. List of Measurement Conditions

The following list indicates the items that can be configured in the measurement conditions. For details on each item, refer to "6.4. Detailed Description of Measurement Conditions".



^{*1} May not be able to be set, depending on the other settings.

^{*2} The range of available values depends on the model.

6.3.2. Available Measurement Conditions

The available measurement conditions depend on the selected measurement mode.

Measurement condition	Measurement mode			
	Standard	Timer mode	Custom mode	
	measurement mode			
Program ID		Yes		
Heating pattern		Yes		
Temperature		Yes		
Time	(The available item	s differ for each measurem	ent mode and heating	
		pattern.		
	Refer to "6.4.4. Temperature and Time")			
Measurement accuracy	Yes	No	No	
Termination value	No	No	Yes	
Sample mass	No	Yes	Yes	
Measurement basis	Yes			
Minimum displayed (%)	No	Yes	Yes	
Minimum displayed (g)	No	Yes	Yes	
Comparator	Available when the function is enabled in the internal settings.			
(maximum, minimum)	Refer to "8. Internal Settings"			
Correction of measurement				
results				

6.3.3. Default Setting

The default measurement conditions are set as follows.

Measurement condition	MS-74A	MX-53A	MF-53A	ML-53A	
Program ID	P *** (where *** is the program number)				
Measurement mode		Standard me	easurement mode		
Heating pattern		Standa	ard heating		
Temperature		1	105°C		
Time					
Measurement accuracy		MID.			
Termination value	0.02%/min	0.05%/min	0.10%/min	0.20%/min	
Sample mass	5 g				
Measurement basis	Moisture content (standard before drying)				
Minimum displayed (%)	0.001%	0.01%	0.05%	0.1%	
Minimum displayed (g)	0.001 g	0.001 g	0.002 g	0.005 g	
Comparator (maximum,	Do not compare				
minimum)					
Correction of measurement	Do not correct				
results					

6.4. Detailed Description of Measurement Conditions

This section provides a detailed description of the measurement conditions and the method for configuring the settings.

The following keys are used to configure the settings.

Operation Keys

Key swit	ch	Function and operation
(SELECT)	SELECT	Enters the mode for changing the measurement conditions.
		Moves to the next selection.
	\uparrow	Changes the value of the selected measurement condition.
PRINT /ENTER	ENTER	Saves the values configured for the measurement conditions.
STOP ON:OFF /RESET	STOP, RESET	Exits without saving the values configured for the measurement conditions.

6.4.1. How to Select Measurement Conditions

Step	Description	Example Display
1.	Switch to the mass display.	PROD MODE NATION SET TEMP. SE D
2.	Press the SELECT key.	SELECT
3.	The measurement mode flashes, and the product switches to the screen for changing the measurement conditions.	PROD MODEL PATTERN SET TEMPS. 1 S.E. d. PATTERN SET TEMPS. 1 U.S. T.
4.	The selected item changes each time the SELECT key is pressed. The flashing item is the currently selected item.	SELECT

6.4.2. Measurement Modes

Mode name	Description of operation		
Standard mode	The standard mode for configuring the main parameters only.		
	The sample mass, termination value, minimum displayed (%), and		
	minimum displayed (g) are automatically set according to the		
	measurement accuracy. (Refer to "6.4.5. Measurement Accuracy ".)		
Timer mode	The mode for configuring the heating time. (1 to 480 min)		
Custom mode	The mode for setting the termination value (change in moisture content) to		
	an arbitrary value.		

Changing the Measurement Conditions

	ing the Medediement conditions	
Step	Description	Example Display
1.	Refer to "6.4.1. How to Select Measurement Conditions" to switch the operation for changing the measurement mode. The current measurement mode flashes. \(\) \(\) \(\) \(\) keys Change the measurement mode.	5 E d : Standard mode E , ME: Timer mode E 5 E M: Custom mode St d Maist Maist

6.4.3. Heating Pattern

Heating pattern name	Temperature change	Description
Standard heating		Maintains the set temperature.
Slow heating		Gradually raises the temperature over time until the set temperature is reached. Then maintains the set temperature.
Step heating		Enables you to set two temperatures. Set the two temperatures and the time to maintain the first temperature.
Rapid heating		Performs heating for approx. three minutes at 200°C. Then maintains the set temperature.

Changing the Heating Pattern

Chang	Jing the neating Fattern	
Step	Description	Example Display
1.	Refer to "6.4.1. How to Select Measurement Conditions" to select the operation for changing the heating pattern. The current heating pattern flashes. \(\rightarrow \) keys Change the heating pattern.	: Standard heating : Slow heating : Step heating : Step heating

6.4.4. Temperature and Time

Arbitrary values can be set for the heating temperature and time.

Temperature: 30 to 200°C (in 1°C increments)

Time: 1 to 480 min (1 min increments)

The available temperature and time values differ according to the measurement mode and heating pattern. The table below indicates the available temperatures and times for each condition.

Heating pattern	Available temperature and time
Standard heating	(1) Temperature (2) Overall measurement time*1 (2)
Slow heating	(1) Temperature (2) Time step 1 (3) Overall measurement time*1 (3) (1)
Step heating	(1) Temperature step 1 (2) Time step 1 (3) Temperature step 2 (4) Overall measurement time*1 (4) (2) (3)
Rapid heating	(1) Temperature (2) Overall measurement time*1 (2) Approx. 3 min (fixed) (1)

^{*1} The value set for the overall measurement time can only be configured when the measurement mode is set to the timer mode.

Changing the Temperature

Chan	Changing the Temperature					
Step	D	escription		Example Display		
1.	Refer to "6.4.1. How to Conditions" to select the temperature. • The temperature. • The information according to the pattern.	ne operation for one operation for o	changing the set flashes.	+1°C (200°C maximum) -1°C (30°C minimum) PROD MODE PATIENT SET THE SE		
	Heating pattern	Selected temperature	Main display	PROO MODE PATTERN SET TENT. TIME ACCURACY TARGET 5 Ed = 10.5 to 10.00 min S.0 g		
	Standard/slow/rapid	Temperature	Program ID	5EEP / % mojst		
	Step	Temperature step 1	SEEP I	Example step 1		
	Step	Temperature step 2	SEEP 2	PROS MOSE MATIEND SET TEMP. TIME ACCURACY TARGET 1 5td - 105 to 100 min Miss. S.C.s		
	↑ ↓ keys Change the set tem	perature value.		Example step 2		

Changing the Time

Step	Description		Example Display	
1.	Refer to "6.4.1. How to Select Measurement Conditions" to select the operation for changing the time. The time that is currently set flashes. The information displayed for the measurement value differs according to the measurement mode and heating pattern.		+1 min -1 min FROO, MODE MATTERN SET TEMP. 1 5 Ed 10 5 c 100 min (MEL) 5 C MODE MATTERN SET TEMP. 6 MOIST MOTOR MOTO	
	Condition	Selected time	Part displayed for measured value	PROOF MODE MITTEN SET TEMP. FROM HOUSE MITTEN SET TEMP. FROM HOUSE MODE MODE MODE MODE MODE MODE MODE MOD
	Heating pattern: Slow/step	Time step 1	SEEP I	display
	Measurement mode: Timer mode	Overall measurement time	FoFAL	
	↑ ↓ key Change the se	=		

6.4.5. Measurement Accuracy

This can only be selected with the standard measurement mode.

One of three levels (HI, MID., LO) can be selected for the measurement accuracy.

The termination value, sample mass, minimum displayed (%), and minimum displayed (g) are automatically selected according to the measurement accuracy.

The selected values are as follows.

	Management	Measurement accuracy setting: ACCURACY		
Model	Measurement	Accuracy priority	\leftrightarrow	Speed priority
	conditions	HI	MID.	LO
	Termination value	0.01%/min	0.02%/min	0.10%/min
	Sample mass	10 g	5 g	1 g
MS-74A	Minimum	0.001%	0.0040/	0.01%
IVIS-74A	displayed (%)	0.001%	0.001%	0.01%
	Minimum		0.001 g	
	displayed (g)		0.001 g	
	Termination value	0.02%/min	0.05%/min	0.50%/min
	Sample mass	10 g	5 g	1 g
MX-53A	Minimum	0.01%	0.01%	0.1%
IVIX-55A	displayed (%)	0.0176	0.0176	
	Minimum	0.001 g		
	displayed (g)			
	Termination value	0.05%/min	0.10%/min	0.50%/min
	Sample mass	10 g	5 g	1 g
MF-53A	Minimum	0.05%	0.05%	0.1%
IVIE-55A	displayed (%)	0.05%	0.05%	U. 170
	Minimum	0.002		
	displayed (g)		0.002 g	
	Termination value	0.10%/min	0.20%/min	0.50%/min
	Sample mass	10 g	5 g	1 g
ML-53A	Minimum	0.1%	0.1%	1%
IVIL-JOA	displayed (%)	U. 1 /0	U. 1 70	1 70
	Minimum	0.005 g		
	displayed (g)			

Changing the Measurement Accuracy (Standard Mode Only)

Step	Description	Example Display
1.	Refer to "6.4.1. How to Select Measurement Conditions" to select the operation for changing the measurement accuracy. The current measurement accuracy flashes. \begin{align*} \text{ keys} \\ \text{ Change the measurement accuracy.} \end{align*}	PROG MODEL NATION SET TEMP. ACCURACY TARGET. \$ G 5 to \$ MODEL MID. LO ACCURACY TARGET. \$ G 9 MODEL MID. ACCURACY TARGET. \$ G 9 MODEL MODEL

6.4.6. Termination value


This can only be selected with the custom mode.

Because the moisture decreases as the sample dries, the change in moisture content per unit time decreases. When the change in moisture content per minute becomes lower than the set value, drying is deemed to have ended and measurement stops.

The available settings are as follows.

		Available range of settings				
		MS-74A MX-53A		MF-53A	ML-53A	
2.00	%/min	†	†	†	†	
1.00	%/min					
0.50	%/min				Available	
0.20	%/min			Available	(default setting)	
0.10	%/min		Available	(default setting)		
0.05	%/min	Available	(default setting)		\	
0.02	%/min	(default setting)		\		
0.01	%/min					
0.005	%/min		T			
0.002	%/min			Unavailable		
0.001	%/min	\				

Configuring the Termination Value (Custom Mode Only)



6.4.7. Configuring the Sample Mass

The sample mass can be configured with the timer mode or custom mode.

Set the upper limit value and lower limit value for loading the sample. When the mass is displayed, the average value of the upper limit value and lower limit value is displayed. The amount to load can be adjusted according to the displayed level meter.

If the sample mass is outside the range of setting values when the sample mass is set in the timer mode or custom mode, heating cannot be started by pressing the START key.

CAUTION

- If the sample mass is set to the default value (0 g for both the upper limit and lower limit), the level meter is not displayed and there is no limit on the heating start time.
- If the lower limit is set to 0 g and the upper limit is set to a value other than 0 g, the operation is the same as if 0.1 g was set for the lower limit.
- If the upper limit is set to 0 g and the lower limit is set to a value other than 0 g, the operation is the same as if the maximum value was set for the upper limit. (51 g for the MX-53A, MF-53A, and ML-53A. 71 g for the MS-74A.)
- If a value other than 0 g is set for both the upper limit and lower limit and a value at or below the lower limit is set for the upper limit, an error is displayed then the screen for setting the upper limit is displayed.

Example Level Meter Display

Sample mass	Level meter display
Lower than the set lower limit	
Within range of set values	
Higher than the set upper limit	

Setting the Sample Mass (Timer Mode or Custom Mode Only)

	ne Sample wass (Timer wode or Custom w	
Step	Description	Example Display
1.	The current sample mass value flashes as indicated in "6.4.1. How to Select Measurement Conditions". *Confirm that "TARGET" is displayed above the sample mass. "Lo" is displayed when changing the lower limit and "Hi" is displayed when changing the upper limit. \[\rightarrow \] keys Change the set sample mass (upper limit or lower limit) value.	O.0 to 51.0 g (71.0 for the MS-74A) TOO MODE PATIENT SET IDENTITY
Remarks	Example: Operation when an error occurs An error occurs if the upper limit of the sample mass is set to a value that is smaller than the lower limit. When the heating conditions are confirmed, an error is displayed and the screen for setting the upper limit of the sample mass is displayed.	PROD MODE MATERN SET TEMP. PRINT / ENTER MODE MATERN SET TEMP. (ESEM

6.4.8. Measurement Basis

Unit	Formula of displayed value	Display
Moisture content	W - D	% MOIST
(standard before drying)*1	——— × 100	/W
Moisture content (Atro)	W - D	% MOIST
(standard after drying)*2	× 100	/D
Solids	× 100	% RATIO
Solids	W	D/W
Ratio*2	× 100	% RATIO
Natio	^ 100	W/D
Grams	_	g

- W: Sample mass before drying D: Sample mass after drying
 - *1 Default setting
 - *2 If the sample mass decreases after drying and the measured value exceeds 999%, operation automatically stops because the measurement results cannot be calculated correctly.

Changing the Measurement Basis

<u> </u>	ging the Measurement Dasis			
Step	Description		Example Display	
1.	Refer to "6.4.1. How to Select Measurement Conditions" to select the operation for changing the measurement basis.	1	Moisture content (standard before drying)	% MOIST /W
	The current measurement basis flashes.		Moisture content (standard after drying)	% MOIST /D
	T Love		Solids	% RATIO D/W
	│		Ratio	% RATIO W/D
			Grams	G
		PROO MODE PATTERN SET	ACCURACY TARGET SUR	

6.4.9. Minimum Displayed (Percentage/Grams)

The available minimum selectable for each model is indicated in the table below.

Model	Minimum displayed		
Wiodei	% (percentage)	g (grams)	
	0.001%	0.0001 g	
MS-74A	0.01%	0.001 g	
IVIO-74A	0.1%	0.01 g	
		0.1 g	
	0.01%	0.001 g	
MX-53A	0.1%	0.01 g	
		0.1 g	
	0.05%	0.002 g	
MF-53A	0.1%	0.01 g	
	1%	0.1 g	
	0.1%	0.005 g	
ML-53A	1%	0.01 g	
		0.1 g	

Changing the Displayed Digits (Percentage/Grams)

Onan	ging the Displayed Digits (Fercentage/Grains)	
Step	Description	Example Display
1.	Refer to "6.4.1. How to Select Measurement	↑0.001
	Conditions" to select the operation for changing the	0.01
	displayed digits (to percentage or grams).	↓0.1 * The selectable
	The displayed digits that are currently set flash.	number of digits
	When changing the displayed digits for the	differs according
	percentage display, "%" is displayed for the unit.	to the model.
	When changing the displayed digits for the grams	PROO MODE PATTERN ST TEMP. ACCURACY TARGET
	display, "g" is displayed for the unit.	0.00 (1.86)
	↑ ↓ keys	Example "%" display
	Change the displayed digits that are set.	PROD NACON PATIENT ST. TIMPP. 1 0 5 c. ACCURATY TARGET S.U.g. 1 0 5 c. ACCURATY TARGET S.U.g. 1 0 5 c. ACCURATY TARGET S.U.g.
		Example "g" display
		g diopidy

6.4.10. Comparator Values

You can set an upper limit and lower limit for the comparator.


To configure the comparator function, it must first be enabled in the internal settings.

You can set an upper limit and lower limit for the comparator that are between 0.0 to 999.9%.


The comparator result is displayed on the screen when measurement stops and is appended to the GLP output and output for the measurement result of the data memory function.

CAUTION

- If the comparator function is disabled in the internal settings, the comparator result is not displayed.
- If the comparator is set to the default value (0% for both the upper limit and lower limit), the comparator result is not displayed.
- If the upper limit of the comparator is set to 0% and the lower limit is set to a value other than 0%, only the lower limit is compared.
- If a value other than 0% is set for the upper limit of the comparator and a value at or above the upper limit is set for the lower limit, an error is displayed then the screen for setting the upper limit is displayed.



Display of moisture analyzer



GLP output (output together when info = 1)

Configuring the Upper Limit and Lower Limit of the Comparator

Configu	ring the Upper Limit and Lower Limit of the 0	Comparator
Step	Description	Example Display
1.	Set [P (comparator mode) in Pr [Fnc (additional functions for measurement conditions) to (enabled) in "8. Internal Settings".	
2.	Refer to "6.4.1. How to Select Measurement Conditions" to select the operation for changing the comparator values. Confirm that the current comparator settings are flashing. "CP" is displayed for the mode. # , is displayed when changing the upper limit of the comparator. L p is displayed when changing the lower limit of the comparator.	"CP" is The proof of the parties of
Remarks	Example: Operation when an error occurs An error occurs if a value lower than the lower limit is input for the upper limit of the comparator. When the heating conditions are confirmed, an error is displayed and the screen for setting the upper limit of the comparator is displayed.	PRINT /ENTER PROOF MATIEN SET TEMP. ACCURACY TARGET S.G. MOIST PRINT /ENTER PROOF MATIEN SET TEMP. ACCURACY TARGET S.G. MOIST ACCURACY TARGET S.G. MOIST MOIST MOIST MOIST

6.4.11. Correction of measurement results

The result of measuring the moisture content can be corrected.

Model	Range of corrected result values
MS-74A	-9.999% to 9.999%
MX-53A	-9.99% to 9.99%
MF-53A	-9.95% to 9.95%
ML-53A	-9.9% to 9.9%
Default setting (no correction)	0%

Formula

The displayed moisture content equals the moisture content that is actually measured plus the correction value

CAUTION

- If the measured value is negative, 0% is displayed for the moisture content.
- Correction is not performed if the correction value is 0% or moisture content correction is disabled.
- The correction value is appended to the GLP output.

Correction of measurement results

Step	Description	Example Display
1.	Set pFF 5EE (moisture content measurement result correction) in Pr[Fnc (additional functions for measurement conditions) to { (enabled) in "8. Internal Settings".	
2.	Refer to "6.4.1. How to Select Measurement Conditions" to select the operation for changing the result correction value. Confirm that the current result correction value is flashing.	*The available range of values differs according to the model.

```
A & D
                                            A & D
MODEL
       MX-53A
                                 MODEL
                                         MX-53A
S/N
       P1234567
                                 S/N
                                          P1234567
ID
        LAB-123
                                 ID
                                           LAB-123
PROGRAM
         No. 1
                                 PROGRAM
                                          No. 1
PROGRAM ID
                                 PROGRAM ID
                                          P 001
        P 001
                                 MODE STANDARD
MODE STANDARD
           MID.
                                             MID.
DRYING STANDARD
                                 DRYING STANDARD
         105 C
                                           105 C
                                                          Correction of measurement results
                                        MOIST /W
UNIT
       MOIST /W
                                 UNIT
OFFSET 1.23 %
                                 OFFSET 1.23 %
INITIAL WEIGHT
                              GLP output (output separately
       5.678 g
FINAL WEIGHT
       4.567 g
RESULT MOIST /W
                            Correction of measurement results
       19.57 %
JUDGMENT
             0K
ANALYSIS TIME
         6.7min
DATE 2024/08/01
TIME 12:34:56
REMARKS
_ _ _ _ _ _ _ _
SIGNATURE
- - - - - - -
```

GLP output (output together when info = 1)

6.4.12. Program ID

A seven character name can be set for the parameter.

The following characters can be used.

0	1	2	3	4	5	6	7	8	9	ı	1	Α	В	\circ	D	Ш	F	G	Н	I	ا	K	Ш	Μ	N	0	Ρ	Q	R	S	Т	J	٧	W	Χ	Υ	Z
	1	2	3	4	5	6	7	8	9	-	1	R	H	Ľ	Z	E	F	្រ	Н	,	L	K	L	M	N	o	P		R	トコ	F	Ш	! ′	77	X	y	7

Changing the Program ID

Step	Description	
9.56	B deditipation	Example Display
	Refer to "6.4.1. How to Select Measurement Conditions" to select the operation for changing the program ID. Confirm that the current program ID is flashing.	PROG MODEL TITLEM SET TWO COLUMN TO THE SET TWO THE SET TWO COLUMN TO THE SET TWO THE SE
2.	Press the	or ਦ
3.	Screen for changing the program ID The selected text flashes. SELECT key Selects the text in the next position. or \int key Changes the selected text. ENTER key Saves the string that is currently displayed and exits. STOP key Exits without saving the string that is currently displayed.	FROG . 3 SELECT

6.5. Examples of Changing the Measurement Conditions

6.5.1. Example 1 (Standard Conditions)

This example describes how to configure the following conditions for program number 2 with the MX-53A.

Measurement condition	Set value		Description/purpose
Program number	2		
Program ID	No change.		
			The sample amount and termination value
Measurement mode	Standard mode	5 Ł d	for moisture content measurement are
weasurement mode	Standard mode	300	automatically set based on the set
			measurement accuracy.
Heating pattern	Standard heating		Heating is performed at a constant
Heating pattern	Standard heating	I	temperature.
Temperature	Heating temperature	150°C	
Measurement			This can only be selected with the standard
	High	HI	mode. (Refer to "6.3.2. Available
accuracy			Measurement Conditions".)
Measurement basis	Moisture content	% MOIST	
weasurement basis	(standard before drying)	/W	

Step	Description	Operation
1.	Press the PROGRAM key with the mass displayed to display the screen for selecting the measurement conditions.	PROGRAM PRO
2.	Press to make 2 flash. *	PION MODE PATTERN SET TEMP. ACCURACY TARGET S.D.9 MOIST POOL NODE PATTERN SET TEMP. ACCURACY TARGET S.D.9 MOIST MODE PATTERN SET TEMP. ACCURACY TARGET S.D.9 MOIST MOIST
3.	Press the ENTER key to confirm the program number.	PRINT /ENTER PRINT /ENTER PRINT /ENTER ACCURACY TARGET S.D. g MOIST PRINT /ENTER ACCURACY TARGET S.D. g MOIST PRINT /ENTER ACCURACY TARGET S.D. g MOIST
4.	Press the SELECT key to display the screen for changing the measurement conditions.	SELECT SELECT

Step	Description	Operation
5.	Press the SELECT key several times to display the screen for changing the temperature setting.	Press several times Programmes Programmes Programmes Accuracy target (MID) 5.0 g MOIST Programmes Accuracy target (MID) 5.0 g MOIST Programmes Accuracy target (MID) 5.0 g MOIST MOIST MOIST MOIST
7.	Press the	PROG MODE PATIENT SIT TIME PROG MODE PATIENT SIT TIME ACCURACY TARGET S. G. 9 MOIST PROG MODE PATIENT SIT TIME ACCURACY TARGET S. G. 9 MOIST PROG MODE PATIENT SIT TIME ACCURACY TARGET S. G. 9 MOIST
	changing the accuracy.	SELECT MODE MATIEN SET INF. SET INF. SET INF. ACCURACY TARGET S.U. MODE MATIEN SET INF. MODE MATI
8.	Press the	PROG MODE PATTERN SET TEMP. PROG MODE PATTER

Step	Description	Operation
7.	Press the SELECT key to display the screen for changing the measurement basis.	PROD MODE PATIENT SET TEMP. SELECT SELECT SELECT FROM MODE PATIENT SET TEMP. SELECT ACCURACY TARGET TOUG MODE PATIENT SET TEMP. SELECT MODE PATIENT SET TEMP. SELECT MODE PATIENT SET TEMP. MODE PATIENT SET TEMP
8.	If necessary, press the	PROD MODE MITTEN SET TEMP. 150 c
9.	Press the ENTER key to save all the settings. End is displayed, then the screen switches to the mass display. To perform moisture content measurement with the changed settings, refer to "5. Measurement ".	PROD MODE PATIEN SET TIME. PROD MODE PATIEN SET TIME. ACCURACY TARGET TO THE TOTAL TO THE TOTA

6.5.2. Example 2 (Complex Conditions)

This example describes how to configure the following conditions for program number 3 with the MX-53A.

Measure	ment condition	Set value	Description/purpose
Program number		3	
Program ID		No change.	
Measurement mode	Timer mode	E ,ME	Measurement stops when a certain period of time has elapsed since measuring the moisture content.
Heating pattern	Standard heating		Heating is performed at a constant temperature.
Temperature	Heating temperature	120°C	
Time	Heating time	15 min	
Sample mass	Hi	11 g	
Sample mass	Lo	9 g	
Measurement basis	Moisture content (standard after drying)	% MOIST /D	
	Percentage	0.1%	*The available values differ according to the
Minimum displayed	Grams	0.01 g	model. Refer to "6.4.9. Minimum Displayed (Percentage/Grams) ".
Camananatan	Hi	010.0%	
Comparator	Lo	008.0%	
Correction of measure	ement results	1.00%	Added to the moisture content.

Preparing to Configure the Measurement Conditions

Enable the comparator and correction of measurement results functions in the internal settings. For details on the internal settings, refer to "8. Internal Settings".

Step	Description	Category	Setting
1.	Press and hold the SELECT key (for approx. two seconds) with the mass displayed to display b \$\pi \sigma r \cdots\$	Press and hold (for approx. two seconds) BASFoc "Environment/Display"	
2.	Press the SELECT key several times to display the additional functions (Pr[Fnc) for the measurement conditions.	Press several times	

Step	Description	Category	Setting
3.	Press the ENTER key to enter the additional functions (Pr[Fnc) for the measurement conditions.	"Additional Functions for Measurement Conditions"	Comparator Mode"
4.	Use the		*Comparator Mode"
5.	Press the SELECT key to display the setting for the result correction of moisture content measurement.	SELECT	"Moisture Content Measurement Resul Correction" "oFF"
6.	Use the		"Moisture Content Measurement Result Correction" "oN"
7.	Press the ENTER key to confirm the changes.	PRINT /ENTER Dout "Data Output"	
8.	Press the RESET key to exit the screen for changing the settings. The screen returns to the mass display.	ON:OFF /RESET	

Step	Description	Operation
1.	Press the PROGRAM key with the mass displayed to display the screen for selecting the measurement conditions.	PROGRAM PRO
2.	Press the	PROG MODE MATTERN SET TEMP. **ROOD MODE MATTERN SET TEMP. **ROOD MODE MATTERN SET TEMP. **ACCURACY TARGET **NOTE MATTERN SET TEMP. **ACCURACY TARGET **ACCUR
3.	Press the ENTER key to confirm the program number.	POOD PATIENT SET TEMP. PRINT PROOF PATIENT SET TEMP. PRINT PRINT PROOF PATIENT SET TEMP. PRINT PROOF PATIENT SET TEMP. GEACURACY TARGET SET
4.	Press the SELECT key to display the screen for changing the measurement conditions.	PROC. MODE PATIEN SET TEMP. SELECT ACCURACY TARGET S. 0 g MODE PATIEN SET TEMP. ACCURACY TARGET S. 0 g MODE PATIEN SET TEMP. SELECT MODE PATIEN SET TEMP. SELECT SELECT MODE PATIEN SET TEMP. MOD PATIEN SET TEMP. MODE PATIENT SET TEMP. MODE PATIENT SET TEMP. MODE PATIEN

Step	Description	Operation
5.	Press the SELECT key once to display the screen for changing the measurement mode.	Press several times
		Press several times Pros Several times Pros Several times 105 % ACCUMACY TARGET S.0 g Mes S.0 g Mes S.0 g Mes S.0 g
6.	Press the key to display £ , M £.	PROG NOTE PATIENT SET 15M2. ACCURACY TARGET S.O.9 PO
	*The	PROG MODE PATIENTS SET TIMP. SET TIME
7	Duran the CELECT key as your times to display	3 E.ME — 185 % 18.8 min % moist
7.	Press the SELECT key several times to display the screen for changing the temperature setting.	PROD MODE WITHOUT SET TEMP. SET TIME. 3 E IME 105 to 1000 min SELECT
		PROD MODE INTERN SET TIME SET TIME PUBLIC TO THE MINING SET TIME MOIST
8.	Press the	PROD MODE NATION SET TIME SET TIME 105 % 1000 min 96 MOIST
	*The	P 120 9 MOIST

Step	Description	Operation
9.	Press the SELECT key to display the screen for changing the time setting.	P G 3 % MOIST SELECT
		BOOK MATTERN SET TIME
10.	Press the	PROD MODE MATTERN SIT TIME SET TIME THE PRODUCT OF
	*The ↑ ↓ keys enable you to change the value.	Press several times FROO MODE PATIENT SET TEMP. SET TIME. SET
11.	Press the SELECT key to display the screen for changing the sample mass upper limit setting.	PROG MODE PATTERN SET LIMB SET
		PROD MODE MATHEM SET LIME SET LIME TARGET AND BET LIME TO SET LIME
12.	Press the	PROG MODE MATTERN SET TIME SET TIME TABLE TABLE TO SET TIME TO SET TIME TABLE TABLE TO SET TIME TABLE
	*The	Press several times Proce Mode MITTERN SET TIME SET TIME 12.0 % 15.0 min 1.0 % MOIST

Step	Description	Operation
13.	Press the SELECT key to display the screen for changing the sample mass lower limit setting.	FROO MODE NATION SET TIMP, SET TIME TARGET 3 E ITTE 120 c 150 min 100 s MOIST
		PROCE MODE MATTERN SET TEMP, SET TIME 3 E / IT E - 1 2 0 - 1 5 0 min 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0
14.	Press the	PROG MODE PATIENT SET TIME SET TIME TARGET TO SET TIME
	*The	Press several times Pros Model Matters SET ISME SET ISME 15.0 min 1446ET 30.0 Molest 15.0 min 26.0 Molest Williams 15.0 Molest William
15.	Press the SELECT key to display the screen for changing the unit setting.	PROOF MODE PATTERN SET TEMPS SET TIME TARGET SET TEMPS SET TIME SET TEMPS SET TIME SET TEMPS SET TIME SET TEMPS SET TIME SET TIME SET TEMPS SET TIME SET TEMPS SET TIME SET TI
		P
16.	Press the ↓ key to display [%] Moist. *The ↑ ↓ keys enable you to change the unit.	POS MODEL NATION SET TIME, SET TIME, 12.0°, 15.0° min, 10.0°, 10.
		PROD MODE PATTERN SET TIME TARGET 10.0 g 1.20 c 15.0 min 10.0 g Molso

Step	Description	Operation
17.	Press the SELECT key to display the screen for changing the decimal point position setting for the percentage display.	SELECT PROOF MADE PATIENT SET TIMP. SET TIME 100 g MOIST SELECT SELECT SELECT MADE PATIENT SET TIMP. SET TIME. 100 g MOIST AMOST JUNE 100 g MOIST MOST JUNE 100 g MOIST SELECT MAST JUNE 100 g MOIST MARGET JUNE 10
18.	Press the	PROOF MODE PATIENT SET TEMP. TIME 100 9 PROOF PATIENT SET TEMP. 100 9 PROOF PATIENT SET TEM
19.	Press the SELECT key to display the screen for changing the decimal point position setting for the grams display.	PROD MODE PATIENT SET 15MP, TIME TARGET 1209 SELECT SELECT FROM MODE PATIENT SET 15MP, TIME TARGET 1209 SELECT TARGET 1209 SELECT TARGET 1209 SELECT TARGET 1209 Grant 1209 Grant 1200 Gra
20.	Press the	PROO MODE PATIENT SET TEMP. 12.0 o 15.0 min 1 / 0.0 g PROO MODE PATIENT SET TEMP. 12.0 o 15.0 min 1 / 0.0 g

Step	Description	Operation
21.	Press the SELECT key to display the screen for changing the maximum value setting of the comparator. *This is only displayed if the setting for the comparator function ([P) is set to { (enabled) in the internal settings. For information on changing the internal settings, refer to "8. Internal Settings".	SELECT SELECT
22.	Press the	Press several times Programmen set tamp. Press several times Programmen set tamp. Pr
23.	Press the SELECT key to display the screen for changing the minimum value setting of the comparator. *This is only displayed if the setting for the comparator function ([P]) is set to { (enabled) in the internal settings. For information on changing the internal settings, refer to "8. Internal Settings".	SELECT MODE MATHEM SET TEMP, TIME SELECT MODE MATHEM SET TEMP, TIME 12.07 to 15.07 min 1 MODE MATHEM SET TEMP, TIME 12.07 to 15.07 min 1 MODE MATHEM SET TEMP, TIME 12.07 to 15.07 min 1 MODE MATHEM SET TEMP, TIME 12.07 to 15.07 min 1 MODE MATHEM SET TEMP, TIME 12.07 to 15.07 min 1 MODE MATHEM SET TEMP, TIME 12.07 to 15.07 min 1 MODE MATHEM SET TEMP, TIME 12.07 to 15.07 min 1 MODE MATHEM SET TEMP, TIME 12.07 to 15.07 min 1 MODE MATHEM SET TEMP, TIME 12.07 to 15.07 min 1 MODE MATHEM SET TEMP, TIME 12.07 to 15.07 min 1 MODE MATHEM SET TEMP, TIME MODE MATHEM SET TE
24.	Press the	Press several times Programme of the control of th

Step	Description	Operation
25.	Press the SELECT key to display the screen for changing the correction of measurement results setting. *This is only displayed if the setting for moisture content measurement result correction (aFF 5EE) is set to { (enabled) in the internal settings. For information on changing the internal settings, refer to "8. Internal Settings".	SELECT SET SET SELECT SELECT SECRET SET SET SELECT SELE
26.	Press the	Press several times \$\int_{\text{0.0}}^{\text{0.0}}\text{\frac{\psi}{\psi}}\$
27.	Press the ENTER key to save all the settings. End is displayed, then the screen switches to the mass display. To perform moisture content measurement with the changed settings, refer to "5. Measurement ".	PRINT /ENTER PRINT /ENTER ST LIME - 1200 c 1500 min 1000 g g

7. Function Tests and Adjustment

This section describes the function tests included in the product for checking operation and the sensitivity adjustment for the mass sensor and heating temperature.

7.1. Function Tests and Adjustment Modes

The product contains the following function tests and adjustment modes.

Name	Display	Description
Moisture content measurement check 1	CHECK MOIST	Uses a test sample (sodium tartrate dihydrate) to check whether moisture content measurement is performed correctly.
RSTEMP	RSEEMP	Automatically determines the recommended heating temperature by performing test heating of a sample for which the appropriate heating temperature is unknown.
Heater check	EHE E K	Confirms that the heater is operating.
Mass sensor sensitivity adjustment		Adjusts the sensitivity of the mass sensor.
Heating temperature adjustment	F-CAT	Adjusts the heating temperature.

7.2. Test Sample Function Check

Regarding the test sample (sodium tartrate dihydrate)

- Sodium tartrate dihydrate (Na₂C₄H₄O₆/2H₂O) can be used for checking the performance of the moisture analyzer. Sodium tartrate includes 15.66% moisture in theory but this value differs according to how the substance is stored.
- Normally, the following measurement method will give a moisture content of 15.0 to 16.0% (standard before drying).
- Sodium tartrate is also used as a food additive, but may irritate the eyes and nose. If it gets on your skin, wash it away with water.
- Dispose of the sodium tartrate after measurement as burnable waste. It cannot be reused.
- Sodium tartrate is included with the MS-74A/MX-53A.
 For the MF-53A/ML-53A, sodium tartrate is available separately.

CAUTION

• If the sample tray is hot before measurement starts, measurement error may occur.

Step	Description	Operation
1.	Description Press and hold the PROGRAM key (for approx. two seconds) with the mass displayed to display moisture content measurement check 1 ([HE[K MOIST]).	Operation PROGRAM PROGRAM Long press (for approx. two seconds) CHECK MOIST MITTEN MITTEN MITTEN MITTEN SECONDS) ACCURACY MOIST ACCURACY

Step	Description	Operation
2.	Press the ENTER key to switch to moisture	
	content measurement check 1 ([HE[II MOIST).	CHECK MOIST
	The measurement conditions are automatically set	PRINT
	to the following recommended conditions.	/ENTER
	Measurement conditions	PROGREM MODE PATTERN SET TEMP. C. H. S. H. S. H. S. H. S. H. O
	Measurement mode: Standard measurement	
	mode	
	Heating pattern: Standard heating	
	Temperature: 160°C	
	Measurement accuracy: MID.	
	Sample mass	
	Maximum mass value: 6.0 g	
	Minimum mass value: 4.0 g	
	Measurement basis: Moisture content	
	(standard before drying)	
	Comparator	
	Maximum: 16.0%	
	Minimum: 15.4%	
	To return to the mass display without executing the	
	check, press the STOP key.	
3.	Press the RESET key to reset the displayed	PRODUMEN MODEL PATTERN SET TEMP. C.M.: 5Ed - 15G- S.G. TO I C 5.G.
	mass value to zero.	
		ON:OFF /RESET
		PROGREM MODEL PATTERN SET TEMP. 1500 C SUBJECT TARGET SUBJECT TAR
4.	Place the test sample flat on the sample tray.	PROGREM MODEL PATIENT SET TEMP. 1500 C
		Bad Good FROMEN MODE PATIENT SET TEMP. CH ! 5Ed - 15 Gr. S.U. D
		5.U 1 9

Step	Description	Operation
5.	Close the lid, then press the START key to start measuring the moisture content.	PRODUKEN MODE PATTERN SET TEMP. C.K. 1. 5 E.d. — 1800 % S.O. 3 9 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1
	Approx. 10 minutes later, the measurement result is displayed. The product is operating normally if the	START
	measurement result is between 15.4 and 16.0% (if a li is displayed by the comparator function).	<u>S È PRÉ</u>
		PATTERN LEME 2 5 % TIME sec 1 Mg sec 1
		Wait for measurement to stop (approx. 10 min)
		End all Marties 1500 to 800 min 1500 % Moist
6.	The product is operating normally if the measurement result is between 15.4 and 16.0% (if It is displayed by the comparator function).	End of Miller 150 to 80 min
	If GLP output is set, the result of checking the product functionality with a test sample is output after the operation is finished.	SELECT
	(Refer to "inFo (GLP output)" in "dout (data output)" in "8. Internal Settings".)	Std MATTERN SET TEMP. 105 % ACCURACY TARGET 5.0 5.0 5.0 5.0 5.0 5.0 5.0 5.0 5.0 5.0
	For information on the output result, refer to "9.3.3.	
	9.3.3. Test Sample Output for Function Check".	
	Press the SELECT key to return to the mass	
	display.	

7.3. RS TEMP (Heating Temperature Detection Function)

Regarding RS TEMP

- This function automatically determines the recommended heating temperature based on changes in the moisture content when performing test heating at multiple temperatures (100 to 200°C) on a sample for which the appropriate heating temperature is unknown.
- The recommended heating temperature is displayed after performing test heating. You can also set the recommended temperature as the heating temperature if required.
- It takes about 30 minutes for the temperature to be determined. Test heating is performed at 100°C, 120°C, 140°C, 160°C, 180°C, and 200°C for five minutes each.
- You can connect to a computer and use the RsTemp function of the WinCT-Moisture software to
 perform test heating for an arbitrary temperature and heating time. (Refer to "13.4.2. RsTemp Software
 for Automatic Heating Temperature Detection")

CAUTION

- RsTemp determines the recommended heating temperature based on the measurement and
 calculated result, but the recommended temperature may not be able to be appropriately determined,
 depending on the sample type and amount.
- When deciding the heating temperature of the sample, also observe the state of the sample over time
 by sight and smell, etc. (whether it melts, burns, smells, or disintegrates) and use that information to
 help decide the heating temperature.

Step	Description	Operation
1.	Press and hold the PROGRAM key (for approx. two seconds) with the mass displayed to display moisture content measurement check 1 ([HE[K]]] MOIST).	PROGRAM Press and hold (for approx. two seconds)
2.	Press the	CHECK I MOIST PSEEMP
3.	Press the ENTER key to switch to moisture content measurement check 1. To return to the mass display without executing the check, press the STOP key.	PRINT PRINT SET TANDS SET

01			0 "
Step	Description Place the sample to check the heating temperature		Operation
4.	of flat on the sample tra		LEMP TO SET INV. SET
	Determine the sample amount based on the		\ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \
	following.		Bad Good
		nple	
		ount	5.0 3 9 g
	content		1.4 4 9
		g or ore	
		r more	
		r more	
5.	Close the lid, then pres		PROG LEMP MITTERN SET TIMES
	test heating.		5.0 3 9 g
			START
			T ŠÈARÉ
			FROO 5 LEMP MIENN 100 - 20 sec
			0.12 %
			•
			•

Step	Description	Operation
6.	Approx. 30 minutes later, the estimated heating temperature is displayed. The operation branches with keys as follows.	5.976 % 5.976 %
	To set the displayed temperature Press the ENTER key while YE5 is flashing. The estimated temperature measured in RSEEMP is set in the measurement conditions.	Temperature display SEL LEGO NO PRINT /ENTER
	To not set the displayed temperature	Applied as set temperature St d
	Press the SELECT key to select No (making it flash). Press the ENTER key while No is flashing. The product returns to the mass display without changing the heating temperature.	Temperature display SELECT SELECT SELECT PRINT / ENTER
		No temperature change St. St. No temperature change

7.4. Self-Inspection

The self-inspection function is used to check the operation of the moisture analyzer. This inspection checks the moisture analyzer for problems when the correct measurement results are not obtained or an operation error is expected. A light is turned on while the function is operating, and temperature control is also checked.

CAUTION

- Do not place flammable objects in the vicinity of the product, as with regular measurement.
- Do not place objects on the heater cover.

Step	Description	Operation
1.	Press and hold the PROGRAM key (for approx. two seconds) with the mass displayed to display moisture content measurement check 1 ([HE[IIII]] MOIST).	Program Press and hold (for approx. two seconds)
		[HE[I/ Moist]
2.	Press the	HERL CHECK HERL CHECK

Step	Description	Operation
3.	Load the sample tray holder and sample tray only, close the heater cover, then press the ENTER key. (Align the sample tray handle with the notch of the breeze break.)	Sample tray only Prepare the tray Close HERE CHECK PRINT /ENTER
4.	The check normally finishes in about one minute.	
	If the check completes without an error A buzzer sounds, [H PR55 is displayed for a certain period of time, then the product automatically returns to the mass display.	CH PRSS FROM SEE TIMES OF TARGET TARGET S.G. O.
	If an error occurs A buzzer sounds and an error is displayed. *For information on handling the error, refer to "15.6. Errors Displayed". Example errors displayed [H no ErrorD HE Err	Example errors displayed [H no Error[]

7.5. Adjusting the Sensitivity of the Mass Sensor

You can use the 20 g or 50 g weight.

It is recommended that you use the 20 g weight for sensitivity adjustment (AX-MX-41 or AD1603-20F1).

CAUTION

- Avoid disturbance such as vibrations or wind during sensitivity adjustment. Sensitivity adjustment may
 not be able to be performed if there is disturbance.
- Because a tall weight may touch the top glass of the heater, use a short weight (20 g weight) where
 possible. When you have no choice but to use a tall weight, perform sensitivity adjustment with the
 heater cover open. Ensure that there is no disturbance such as wind.


Step	Description	Display and key operation	Operation
1.	Open the heater cover, load the tray holder and sample tray, then close the heater cover.		
2.	Press and hold the PROGRAM key (for approx. two seconds) with the mass displayed to display moisture content measurement check 1 ([HE[K I_MOIST]).	Press and hold (for approx. two seconds)	
3.	Press the	CHECK I MOIST OF OF	
4.	Press the ENTER key to switch to mass sensor sensitivity adjustment.	E A L PRINT /ENTER	
5.	The zero point for sensitivity adjustment is displayed. To change the weight value, proceed to step 6. Otherwise, proceed to step 8.	CAL O	

Step	Description	Display and key operation	Operation
6.	Press the SELECT key to display the current weight value.	<u>\$ \tilde{D}\tilde{O}(\tilde{Q}\tilde{\tilde{Q}}\t</u>	
7.	Press the ↑ or ↓ key to change the weight value.		
8.	Press the ENTER key to change the weight value. Press the RESET key to exit without changing the weight value.	SOOO G G PRINT OR ON:OFF /RESET CAL D	
9.	Confirm that there are no objects on the sample tray, then press the ENTER key with the heater cover closed.	[AL []	
10.	Weigh the zero point. Avoid vibrations.	. CAL 0	
11.	The weight value to use for sensitivity adjustment is displayed. Place the weight on the sample tray, then press the ENTER key.	PRINT /ENTER	
12.	Weigh the weight. Avoid vibrations.	. 20	

Step	Description	Display and key operation	Operation
13.	Remove the weight from the sample tray.	End	
14.	If GLP output is set, a sensitivity adjustment record is output after the operation is finished. (Refer to InFa (GLP output) in daut (data output) in "8. Internal Settings".)	GLP output	
	For information on the output result, refer to "9.3.4. Mass Sensor Output for Sensitivity Adjustment".	End	
15.	The product automatically returns to the mass display.	PROG MODE PATIENT SET TEMP. 1 5 b d	

7.6. Adjusting the Heating Temperature

- Place the sensor of the optional temperature adjustment kit (AX-MXA-43) on the tray holder, measure the temperature of the sample tray part, then input the measurement result to the moisture analyzer. This process is performed at 100°C and 160°C.
- Heating is performed at both temperatures for 20 minutes. A buzzer sounds when 20 minutes have elapsed.
- If five minutes elapse without any data input since the buzzer sounded, £ !!P is displayed and the process is canceled. Press any key to return to the mass display.
- For information on operating the temperature display, refer to the instruction manual that came with the temperature adjustment kit.



Step	Description	Operation
1.	Connect the sensor of the temperature adjustment kit to the temperature display.	
2.	Press the ON OFF key for the temperature display of the temperature adjustment kit to turn the temperature adjustment kit on.	ON OFF
3.	Open the heater cover, remove the sample tray, then place the sensor of the temperature adjustment kit on the tray holder.	Sensor Ensure that the top sensor
4.	Close the heater cover. When doing so, ensure that the wire of the temperature sensor is not pushed by the glass inside the heater unit, as it can cause the sensor of the temperature adjustment kit to lift up. Fold back the cable protruding from the sensor as required.	Remain flat Bend the sensor wire so that it does not touch the heater cover.
5.	Press and hold the PROGRAM key (for approx. two seconds) with the mass displayed to display moisture content measurement check 1 ([HE[II MOIST]).	PROGRAM Press and hold (for approx. two seconds) CHECK MATTERN SET THAMPS 15 11 10 10 10 10 10 10 10 10 10 10 10 10


Step	Description	Operation
6.	Press the ↑ or ↓ keys several times to display the heating temperature adjustment (Ł - [ЯL).	CHECK I MOIST or L-CAL
7.	Press the ENTER key to switch to heating temperature adjustment.	E - [AL PRINT PR
8.	Press the START key. The moisture analyzer starts temperature control to heat the sample tray to 100°C.	START START OF 1985 min OF 1
9.	When 20 minutes have elapsed, a buzzer sounds, then 100°C flashes. Press the	or

Step	Description	Operation
10.	Press the ENTER key to confirm the value. After displaying <code>End</code> , the moisture analyzer starts temperature control to heat the sample tray to 160°C.	PRINT /ENTER 188 % 185 min 180 0 [
11.	When 20 minutes have elapsed, a buzzer sounds, then 160°C flashes. Press the ↑ or ↓ key to change the flashing number until it reaches the actual temperature displayed on the thermometer. (Example: 162°C)	or James Jam
12.	Press the ENTER key to confirm the value. After displaying End, the moisture analyzer starts temperature control to heat the sample tray to 160°C.	PRINT /ENTER
13.	If GLP output is set, a heating temperature adjustment record is output after the operation is finished. (Refer to InFa (GLP output) in daut (data output) in "8. Internal Settings".) For information on the output result, refer to "9.3.5. 9.3.5. Output for Heating Temperature Adjustment".	GLP output
14.	The product automatically returns to the mass display.	PROO MODE MATTERN SET THAN 5 COURACY TARGET S.G. S.G. S.G. S.G. S.G. S.G. S.G. S.G

8. Internal Settings

In 8. Internal Settings, you can configure and change the operation and communication of the moisture analyzer. The setting values are retained even when the power cable is removed.

The menu in "8. Internal Settings" is comprised of two levels, categories and settings, and each setting stores a single value. The setting values that are last displayed are enabled. Updated setting values are reflected in the operation of the moisture analyzer after the ENTER key is pressed.



8.1. Procedure

Internal settings display and key operation

0	The O icon is displayed for setting values that are currently enabled.
SELECT	Press and hold (for approx. two seconds) with the mass displayed to switch to the internal settings menu. (Display the categories) It changes the category or setting.
(4)	While a setting is displayed, changes the setting value.
PRINT /ENTER	Displays the setting in the category. Registers the setting value, then proceeds to the next category.
ON:OFF /RESET	While a setting is displayed, cancels the setting and proceeds to the next category. While a category is displayed, exits the internal settings and returns to the mass display.

Procedure

In this example, "the data output mode (P r t)" is set to "auto print (P r t = t)",

and "the data memory function (dRLR)" is set to "dRLR = 1".

Step	Description	Category	Setting
1.	Press and hold the SELECT key (for approx. two seconds) with the mass displayed to display BRSFnc.	Press and hold (for approx. two seconds) BASFnc Environment/Displa	
2.	Press the SELECT key several times to change the category to display "dout".	Press several times dout "Data Output"	
3.	Press the ENTER key to switch to the selected category.	PRINT	ீ <u>"E பீ</u> "Data Output Mode" "Key Mode"
4.	Press the ↑ ↓ keys to change the value of the selected setting and display " { : Ruta ".	or T	*Data Output Mode" "Auto Print Mode"
5.	Press the SELECT key to change the setting to display " dfl h h h.".	SELECT	"Data Memory Function" "of F"

Step	Description	Category	Setting
6.	To change other settings of the same category, repeat steps 4 and 5. To finish changing the settings of the selected category, proceed to step 7.	or T	"Data Memory Function" "aN"
7.	To register the setting, Press the ENTER key to display the next category.	PRINT /ENTER U5b "Serial Interface"	
	To cancel the setting, Press the RESET key to display the next category. The setting value will not be changed.	ON:OFF /RESET U5b "Serial Interface"	
8.	To change the settings of another category, return to step 2. To cancel changing the settings, press the RESET key. The screen returns to the mass display.	ON:OFF /RESET	

8.2. List of Items

Category	Setting	S _i val		Descrip	otion/purpose	
	Pnt (Point)		Ï	. Period	The symbol to display/output for	
	Decimal point		1	, Comma	the decimal point.	
(BasicFuncti	L E d i (Display LED) Backlight brightness			10% to 100%		
Environment/			7	80% by default		
display	P-oFF (Power Off)		ŭ	Off	The display automatically turns off if no operations are	
	Auto power off		1	On (10 minutes)	performed for 10 minutes.	
	「ドレー」と (Calculation Data)		ij.	int: Perform calculations with priority given to the accuracy of the moisture content. The moisture content is calculated wit more digits than the displayed mass.		
	Calculation data		1	DiSPLAy: The moisture content is calculated with the numb of digits for the displayed mass.		
(Clock Adjustment) Clock				'8.4. Checking and ng the Date/Time".	Checks and adjusts the date and time. The date and time are used for output.	
PrG Fnc	[P (Comparator)		Ü	oFF: Do not use the compa	rator function.	
(Pr o g ram F u nc tion)	Comparator mode		1	oN: Use the comparator fur	nction.	
Additional functions for	۵۶۶ 5 E Ł (Off Set)		Ï	oFF: Do not use moistu correction.	re content measurement result	
measuremen t conditions	Moisture content measurement result correction		1	oN: Use moisture content n	neasurement result correction.	

[■] indicates a default setting.

Category	Setting		et lue	Descrip	otion/purpose
	п .		<u> </u>	Key mode	Press the ENTER key to output data.
	Prt (Pr int) Data output mode		1	Auto print mode	When measurement finishes, the data is automatically printed.
			Š	Stream mode	The data is continuously output during measurement.
	98F8		Ĭ	oFF: Do not record the me	easurement results.
	(Data Memory) Data memory function		1	oN: Record the measurem	nent results.
	5 - d		Ï	Output the measurement r	esults only.
	(S end D ata) Sent data		1	Output the measurement r	esults and the temperature data.
	PUSE		Ï	Disabled	Select the interval for data
	(P a use) Data output interval		1	Enabled: Wait 1.6 seconds	output.
dout	info		Ï	Disabled	
(D ata out) Data output	(Information) GLP output		3	device information, measurement results, and The clock data of the moi the date and time. 5EP NE: Outputs the device information, measurement space separately. The clock data of the moi the date and time. FLL EXE: For each measurement results, and The clock data of an extendate and time. 5EP EXE: Outputs the	the signature space together. sture analyzer is used to output measurement results and the rement conditions, and signature sture analyzer is used to output asurement result, outputs (prints) arement conditions, the signature space together. The result is used to output the measurement results and the
			4	space separately.	rement conditions, and signature
<u>U56</u>	UFnc		I	QuicK: Quick USB	
(USB) USB settings	(USB Function)		1	V CoM: Bidirectional virtua	al USB COM
(ID) ID number settings		Ref	er to	"9.2. Configuring the ID Nu	mber".

Category	Setting	Set value	Description/purpose			
	PW (Password)	• <u> </u>		bled bled (restrict use of sture analyzer)	Refer to "11. Password	
PR55md (Password)	Password function	کے	Enal	<u> </u>	Function".	
Password	 PRSSNo.	ADM USER		Administrator password User 1 password entry	entry	
	(Pass word No .) Password registration			\$		
			10	User 10 password entry		
(Initialize Function)	[Lr Fnc (Clear Function) Initialize internal settings	Enables you to restore the default internal settings of the product. Refet to "15.4. Initializing the Settings".				
Initialization function	[Lr RLL (Clear All) Initialize all	Enables you to restore the default settings of the product. Refer t "15.4. Initializing the Settings".				

[■] indicates a default setting.

8.3. Description of Environment/Display Settings

Description of Pnt (decimal point)

Selects the symbol to display and output for the decimal point.

Description of LEd (backlight brightness)

Selects the brightness of the LCD backlight.

Description of P-oFF (auto power off)

The display automatically turns off if no operations are performed for a certain period of time (approx. 10 minutes).

If "PW (the password function)" in "PR55 md (password)" is set to "enabled (LacK = 1 or 2)", the display automatically turns off and the user is logged out if no operations are performed.

CAUTION

- The display does not turn off during heating.
- The display does not turn off while the result is displayed, but it may turn off when the product returns
 to the mass display. (If no operations are performed for a certain period of time (approx. 10 minutes)
 when logged in as the administrator)

Description of [] [-] [(calculation data)

You can select whether to use the internal mass value (with more digits than the displayed mass) to improve the accuracy of calculating the moisture content, or use the number of digits for the displayed mass.

If the internal mass value is used, the accuracy of the moisture content will be higher, but there may be a difference between the measurement result of the moisture analyzer and the moisture content separately calculated from the mass values output after drying and before drying.

8.4. Checking and Configuring the Date/Time

The moisture analyzer contains a date/time function. This mode enables you to check and configure the date and time. If "InFa (GLP output)" is set to "I: $\Pi L INE$ " or "Z: SEP INE" in "daut (data output)" in "8. Internal Settings", GLP output is performed when outputting the moisture content measurement result and when adjusting the mass sensor sensitivity or adjusting the heating temperature. If "InFa (GLP output)" is set to " $3:\Pi LLEXE$ " or "4:SEPEXE", the clock data of an external device is used.

CAUTION

- Do not configure an invalid value (such as a date that does not exist).
- When the backup battery of the clock expires, represent requires a repair at the place of purchase, but functions other than the clock will continue to operate even if the backup battery has expired. The clock function will also operate normally, as long as power is supplied to the moisture analyzer.

Press the keys to configure the date and time.

You can perform the following operations to check and configure the date and time.

Switching to the Mode for Checking the Date and Time

Step	Description	Display and key operation
1.	Press and hold the SELECT key (for approx. two seconds) with the mass displayed to display the "8. Internal Settings" menu.	PROOF INTERN SET TEMPO. 1 SE d
		SELECT COMMON TO SELECT
		(for approx. two seconds)
		685Fnc
2.	Press the SELECT key to match the display with the figure.	SELECT
		Cr 897
3.	Press the ENTER key to switch to checking the time.	PRINT /ENTER
		12.34.56

Checking the Time

Step	Description	Display and key operation
4.	The current time is displayed. (All digits flash) The operation branches with keys as follows.)
	 To change the time, press the	or T
		<u>\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\</u>
		Proceed to "Configuring the Time"
	To check the time, press the SELECT key. Proceed to "Checking the Date" (step 7).	SELECT
		Proceed to "Checking the Date"
	 To finish configuring the settings, press the STOP key. Proceed to "Finishing the Check/Configuration Operation" (step 10). 	ON:OFF /RESET
		StoP
		PrG Fnc
		Proceed to "Finishing the Check/Configuration Operation"


Configuring the Time

Coni	iguring the Time	
Step	Description	Display and key operation
5.	Press the following keys to configure the time. (In the 24-hour format)	<u>) 2:3 4:5 6</u>
	key Increments the value of the flashing digit (+1).*1 key Decrements the value of the flashing digit (-1).*1 SELECT key Moves the cursor.	12:34:56
	*1 Increases or decreases by 30 when changing the number of seconds.	(SELECT)
6.	Press the ENTER key to register the new time. (Press the RESET key to cancel.)	12:34:56
	Proceed to "Checking the Date" (step 7).	PRINT
		End
		24. 1.0
		Proceed to "Checking the Date"

Checking the Date

Che	Checking the Date					
Step	Description	Display and key operation				
7.	The current date is displayed. (All digits flash) The operation branches with keys as follows.	7 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1				
	To change the date, press the	or T				
		Proceed to "Configuring the Date"				
		Proceed to Configuring the Date				
	To check the time again, press the SELECT key. Proceed to "Checking the Time" (step 4).	SELECT				
		7-1-1-1-1-1-1-1-1-1-1-1-1-1-1-1-1-1-1-1				
		Proceed to "Checking the Time"				
	 To finish configuring the settings, press the STOP key. Proceed to "Finishing the Check/Configuration Operation" (step 10). 	ON:OFF /RESET				
		St o P				
		PrG Fnc				
		Proceed to "Finishing the Check/Configuration Operation"				

Configuring the Date



Finishing the Check/Configuration Operation

Step	Description	Display and key operation
10.	The next internal setting (Pri Fnc) is displayed. Press the STOP key to return to the mass display.	PrG Fnc ON:OFF /RESET ON:OFF /RESET O

8.5. Additional Functions for Measurement Conditions

You can enable measurement conditions that are disabled by default.

When a function is enabled, the setting is added to the measurement conditions.

Even if functions are configured in the measurement conditions, they will not operate if they are disabled in the internal settings.

Description of [P (comparator mode)

If $: \square \mathbb{N}$ is set, the comparator setting is added to the measurement conditions.

When a moisture content lower limit and upper limit are set, the comparator result of H ,/a !//L a is added when displaying the moisture content of measurement results, when performing GLP output for the measurement results, and when saving the measurement results with the data memory function.

If $\[\[\] : \[\] \] F F$ is set, the comparator setting is not added to the measurement conditions. (For details, refer to "6.4.10. Comparator Values".)

If $: \square \mathbb{N}$ is set, the correction of measurement results setting is added to the measurement conditions. The set value is added when displaying/outputting the measured moisture content.

Formula

The displayed moisture content equals the moisture content that is actually measured plus the correction value.

CAUTION

• If the measured value is negative, 0% is displayed for the moisture content.

If $\Box : \Box FF$ is set, correction is not performed.

(For details, refer to "6.4.11. Correction of measurement results".)

8.6. Description of Data Output					
8.6.1. Data Output Mode					
The timing of the data output can be switched with "Prt (data output mode)" in "dout (data output)" in "8. Internal Settings".					
Key mode You can press the ENTER key to output the displayed	Internal settings $ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \$				
Auto print mode When moisture content measurement finishes, the measurement for the measurement finishes, the measurement finishes for the measurement finishes, the measurement finishes for the measurement finis	• •				
Stream mode The data is continuously output during measurement. You can also press the ENTER key while the mass o	Internal settings doub Prt = 2				


value and moisture content once.

8.6.2. Data Format

Format output from the virtual COM (USB) and RS-232C: Standard A&D format

(5 - d = 7) and $10 F_0 = 7$ in the internal settings)

- Each item of data includes 15 characters. (Not including the terminator)
- · The state of the data is indicated in two headers.
- The data is signed and is zero-padded (leading spaces are filled with zeros).
- When the data is zero, it is deemed positive.
- · Each item of data includes 3 characters.




Format output with quick USB: NU2 format

(5 - d = 7) and $10 F_0 = 7$ in the internal settings)


- Only values are output.
- When the data is zero or a positive value, it is not signed.

Quick USB



8.6.3. Example Output for Data Format


Sample mass value (data format output when performing measurement with the mass display or "g" for the unit)




When over (positive)

A&D

NU2



When over (negative)



Moisture content (data format output during measurement or after measurement is finished)


* The position of the decimal point in the data depends on the model and the minimum displayed.

 $(5 - d = 7 \text{ and } 10 \text{ F}_{0} = 7 \text{ in the internal settings})$



When adding temperature data to the moisture content data

(5 - d = 1) and $InF_0 = II$ in the internal settings)



A&D NU2

A&D

NU2

9. GLP and ID Numbers

9.1. Main Uses

By setting " $_{I}$ $_{I}$ $_{I}$ $_{I}$ $_{I}$ (GLP output)" to $_{I}$ to $_{I}$ $_{I}$

GLP refers to "Good Laboratory Practice".

GMP refers to "Good Manufacturing Practice".

The data output supporting GLP or GMP includes the moisture analyzer manufacturer name (A&D), model name, serial number, ID number, date, time, and signature. Mass sensor sensitivity adjustment includes the weight used, and heating temperature adjustment includes the set temperature.

The following data supporting GLP or GMP can be output from the RS-232C or USB terminal.

- Record of mass sensor sensitivity adjustment (output when sensitivity adjustment is performed with a weight you have)
- Heating temperature adjustment
 (output when heating temperature adjustment is performed with the temperature adjustment kit)
 - The ID number can be used as the moisture analyzer identification number for maintenance management.
 - The ID number is retained even when the power is turned off and is enabled until a new number is registered.
 - For information on checking/adjusting the date and time, refer to "8.4. Checking and Configuring the Date/Time".
 - When connecting the AD-8127 (multi printer) or AD-8129TH (thermal printer) to the moisture analyzer to print the GLP output, the clock function of the printer can be used to print the date and time.

ADVICE

• When outputting data supporting GLP/GMP, set the print mode of the AD-8127 or AD-8129TH to the dump print mode (DUMP). If the external key print mode (EXT. KEY) was used to print the mass value and moisture content, you can press and hold (for approx. two seconds) the ENT button of the AD-8127 or AD-8129TH to switch between the external print mode and dump print mode.

9.2. Configuring the ID Number

Display Correspondence Table

Refer to the following table to identify the segment display corresponding to each character.

	0	1	2	3	4	5	6	7	8	9	-	u	Α	В	С	D	E	F	G	Н	I	J	K	L	М	Ν	О	Р	Q	R	S	Т	U	V	W	X	Y	Z
	0	1	2	3	4	5	6	7	8	9	•	-	R	3	Ľ	F4	Ε	F	ն	Н	1	J	K	L	M	22	o	P		R	トコ	Ŀ	Ш	! /	W	٧ ٨	ሃ	7
•	_		,	ke	эy							Sp	ace	Э																					\uparrow	ke	Э	\rightarrow

Setting Method (Changing the Internal Settings)

Sett	Setting Method (Changing the Internal Settings)						
Step	Description	Display and key operation					
1.	Press and hold the SELECT key (for approx. two seconds) with the mass displayed to display the "8. Internal Settings" menu.	SELECT)					
		Long press (for approx. two seconds)					
		685Fnc					
2.	Press the SELECT key several times to match the display with the figure.	SELECT					
		Press several times					
		ıd					
3.	Press the ENTER key to input the ID number using the following keys.	PRINT /ENTER					
	SELECT key Moves the flashing digit. \(\begin{align*} \text{key} \cdots \cdots \text{Changes the character of the flashing digit. (+)} \\ \(\begin{align*} \text{key} \cdots \cdots \text{Changes the character of the flashing digit. (-)} \end{align*} \)						

Step	Description	Display and key operation
4.	Press the ENTER key to register the change. (Press the RESET key to cancel without registering the changes.)	LAB-123(PRINT //ENTER End PRSSwd
5.	Press the RESET key to return to the mass display.	ON:OFF /RESET ON:OFF /RESET

9.3. GLP output

To output data supporting GLP or GMP to the AD-8127 (multi printer), AD-8129TH (thermal printer), or a computer, set "InFa (GLP output)" to " ' to ' ' " in "dau' (data output)" in "8. Internal Settings".

The differences between each setting are as follows.

in Fo setting	Measurement result output*1	Clock data
1: ALL INE	Output all	Use internal data
2:5EP INE	Output separately	Use internal data
3: ALL Ext	Output all	Use external device data
Y: SEP EXE	Output separately	Use external device data

^{*1} Measurement result output

Output all: Outputs the "device information", "measurement conditions", and "signature space" together with the measurement results.

Output separately: Outputs the "device information", "measurement conditions", and "signature space" separately from the measurement results.

If you want to manage clock data with the clock function of an external device, it is convenient to set this to "

3: RLL EXE" or "Y: 5EP EXE".

CAUTION

- If the date/time does not match when outputting the clock data in the moisture analyzer ($InF_D = I$ or I), adjust the time/date using " Il Rdd (time)" in "8. Internal Settings".
- Clock data output using an external device is only supported for devices with a clock function that can output the date/time by receiving <ESC>D and <ESC>T. **1
 (AD-8127, AD-8129TH, and RsCom data communication software of WinCT, etc.)
 - *1 <ESC> refers to the escape code (ASCII 1Bh).
- The clock data saved with the data memory function is always the internal data. Eternal device data cannot be used.
- When outputting to a printer, set the AD-8127 or AD-8129TH (multi printer) to the dump print mode (DUMP).

Setting Method (Changing the Internal Settings)

Step	Description	Display and key operation
1.	Press and hold the SELECT key (for approx. two seconds) with the mass displayed to display the "8. Internal Settings" menu.	Long press (for approx. two seconds)

Step	Description	Display and key operation
2.	Press the SELECT key several times to match the display with the figure.	Press several times
		dout
3.	Press the ENTER key.	PRINT /ENTER
		° KEŸ
4.	Press the SELECT key several times to display InF (GLP output).	SELECT
		° ° FF
5.	Press the ↑ and ↓ keys several times to change "inFa (GLP output)" to " {: RLL iNE", " ₹: 5EP iNE", " ₹: 5EP EXE".	
		Press several times
		ALL INE
		SEP INL
		ALL EXE
		SEP EXL
6.	Press the ENTER key to register the change.	PRINT /ENTER
		USЬ

Step	Description	Display and key operation
7.	Press the RESET key to return to the mass display.	ON:OFF /RESET Std Pattern set hand ON:OFF /RESET ACCURACY TARGET S.G.g. Q. Q

9.3.1. Example Measurement Result Output


Example with All Data Output

This method outputs the measurement results together with the device information, measurement conditions, measurement data, and signature space.

Refer to "8. Internal Settings" to set " $_{ID}F_{ID}$ (GLP output)" to " $_{I}$: ALL $_{INE}$ " or " $_{I}$: ALL $_{I}$: ALL

Example Output (1)

When "8. Internal Settings" - ", n F a (GLP output)" is set to "; RLL , NL"



: Space: ASCII 20h <TERM> : Terminator: C_R L_F


C_R : Carriage return: ASCII 0Dh L_F : Line feed: ASCII 0Ah

1	Manufacturer name	8	Heating pattern*1	15	Comparator result*3
2	Model name	9	Measurement basis	16	Measurement time*1
3	Serial number	10	Comparator setting*3	17	Measurement date/time
4	ID	11	Correction of measurement results*2	18	Remarks space*1
5	Program number	12	Sample mass before drying	19	Signature space*1
6	Program ID	13	Sample mass after drying		
7	Measurement mode*1	14	Measurement result		

- *1 Refer to "9.3.2. Description of Printed Information"
- *2 Only printed when correction of measurement results is enabled and the setting value is not 0%
- *3 Only printed when the comparator function is enabled and either the upper limit or lower limit is set to a value other than 0%

Example Output (2)

When "8. Internal Settings" - "In Fo (GLP output)" is set to " \{ : \frac{1}{2} : \frac{1}{2} \text{L} \text{L}"



: Space: ASCII 20h <TERM> : Terminator: C_R L_F

C_R : Carriage return: ASCII 0Dh

L_F: Line feed: ASCII 0Ah

1	Manufacturer name	8	Heating pattern ^{*2}	15	Comparator result*4
2	Model name	9	Measurement basis	16	Measurement time*2
3	Serial number	10	Comparator setting*4	17	Measurement date/time
4	ID	11	Correction of measurement results*3	18	Remarks space*2
5	Program number	12	Sample mass before drying	19	Signature space*2
6	Program ID	13	Sample mass after drying		
7	Measurement mode*2	14	Measurement result		

- *1 The order and notation used for the year, month, and day depend on the version of WinCT and the configuration of the computer.
- *2 Refer to "9.3.2. Description of Printed Information"
- *3 Only printed when correction of measurement results is enabled and the setting value is not 0%
- *4 Only printed when the comparator function is enabled and either the upper limit or lower limit is set to a value other than 0%

When Outputting Data Separately

In this example, the device information, measurement conditions, and signature space are printed at a different time to the measurement data.

This enables you to save paper when the measurement conditions are the same.

Refer to "8. Internal Settings" to set " $_{ID}F_{ID}$ (GLP output)" to " $\not\supseteq$: 5EP $_{INE}$ " or " Y : 5EP $_{EXE}$ ".

How to Print the Device Information and Measurement Conditions

	ulions	5
Step	Description	Display and key operation
1.	Press and hold the ENTER key with the mass displayed.	PRINT
2.	Press the SELECT key to display L ,5Ł. When the data memory function is enabled (when " dRLR (data memory function)" is set to "!"), out and [Lr are	SFLECT
	also displayed.	L 15E
3.	Press the ENTER key to output the "device information" and "measurement conditions". When the output is complete, the product automatically returns to the mass display.	L , 5 E PRINT /ENTER "Device information" and
		"measurement conditions" output Str Marien Str Marien Str Marien Str Str

How to Print the Measurement Data


The method for printing the data depends on the internal settings of the moisture analyzer. (For details, refer to "8.6.1. Data Output Mode".)

Prt setting	Output method								
Ũ	Press the ENTER key with the measurement result displayed.								
When measurement finishes, the "measurement data" is automatically printed.									
	Press the ENTER key with the measurement result displayed.								
Ž	(This method is not appropriate for outputting only the "measurement data" while heating,								
	because the moisture content will be continuously output.)								

How to Print the Signature Space

Step	Description	Display and key operation
1.	Press and hold the ENTER key with the mass displayed.	Long press (for approx. two seconds) LISE or
2.	Press the SELECT key to display 5 , []. * When the data memory function is enabled (when " dRLR (data memory function)" is set to " ;"), out and [Lr are also displayed.	SELECT 5 , G
3.	Press the ENTER key to output the "signature space". When the output is complete, the product automatically returns to the mass display.	"Signature space" output "Signature space" output

When ", ¬, F □ (GLP output)" in "8. Internal Settings" is set to " ? : 5 E P ¬, N L"



: Space: ASCII 20h <TERM> : Terminator: C_R L_F

C_R : Carriage return: ASCII 0Dh L_F : Line feed: ASCII 0Ah


1 Manufacturer name 8 Heating pattern*1 15 Comparator result*3 2 Model name Measurement basis Measurement time*1 9 16 3 Serial number 10 Comparator setting*3 17 Measurement date/time 4 ID 11 Correction of measurement results*2 18 Remarks space*1 5 Signature space*1 Program number 12 Sample mass before drying 19 6 Program ID 13 Sample mass after drying 7 Measurement mode*1 14 Measurement result

*1 Refer to "9.3.2. Description of Printed Information"


- *2 Only printed when correction of measurement results is enabled and the setting value is not 0%
- *3 Only printed when the comparator function is enabled and either the upper limit or lower limit is set to a value other than 0%

9.3.2. Description of Printed Information

Measurement Mode, Measurement Conditions



Heating Pattern



Comparator


This is only printed when the "comparator mode ([P]" in "8. Internal Settings" is set to " $_{\square}N$: $[P = { }$ " and either the upper limit or lower limit is set to a value other than 0%.

Item		Printed part and description	
Set value		CP HI 21.0 % LO 18.0 %	Comparator setting upper limit value Comparator setting lower limit value
	Result when upper limit value is less than moisture content	JUDGMENT HI	Comparator result
Result	Result when lower limit value is less than or equal to moisture content result and moisture content result is less than or equal to upper limit value	JUDGMENT OK	Comparator result
	Result when moisture content result is less than lower limit value	JUDGMENT LO	Comparator result

Result Correction

The correction value adding when calculating the final measurement result from the moisture content measurement result.

Only printed when "moisture content measurement result correction ($_{\square}FF$ $_{5}EE$)" is set to " $_{\square}N$: $_{\square}FF$ $_{5}EE$ = $_{4}$ " in "8. Internal Settings" and the correction value is not 0%.



Measurement basis

Measurement Basis	Printed part	Formula of displayed value	Display
Moisture content (standard before drying)*1	UNIT MOIST/ W	$\frac{W-D}{W} \times 100$	% MOIST /W
Moisture content (Atro) (standard after drying)*2	UNIT MOIST/ D	<u>W − D</u> × 100	% MOIST /D
Solids	UNIT RATIO D/W	× 100	% RATIO D/W
Ratio*2	UNIT RATIO W/D		% RATIO W/D
Grams	UNIT g	*3	g

W: Sample mass before drying

D: Sample mass after drying

*1 Default setting

*3 The moisture content result is derived from the moisture content (standard before drying).

^{*2} If the sample mass decreases after drying and the measured value exceeds 999%, operation automatically stops because the measurement results cannot be calculated correctly.

Measurement Date/Time

The measurement date/time outputs the date/time of the clock in the moisture analyzer.


The date order (YYYYMMDD, MMDDYYYY, or DDMMYYYY) follows the setting in "8.4. Checking and Configuring the Date/Time".

For information on adjusting the clock, refer to "8.4. Checking and Configuring the Date/Time".




Remarks Space

Enables you to enter a comment such as the name of the measured sample.



Signature Space

Enables you to write your signature.




9.3.3. Test Sample Output for Function Check

The GLP output when performing a function check with a test sample is indicated below.

Example Output

When "8. Internal Settings" - "InFa(GLP output)" is set to " : FLL INE"



: Space: ASCII 20h <TERM> : Terminator: C_R L_F

C_R : Carriage return: ASCII 0Dh L_F : Line feed: ASCII 0Ah

- Manufacturer name
- 2 Model name
- 3 Serial number
- 4 ID
- 5 Test mode
- 6 Test sample name (sodium tartrate)

- 7 Sample mass before drying
- 8 Sample mass after drying
- 9 Measurement result
- 10 Comparator result
- 11 Measurement time*1
- 12 Measurement date/time


^{*1} Refer to "9.3.2. Description of Printed Information"

9.3.4. Mass Sensor Output for Sensitivity Adjustment

The GLP output when performing sensitivity adjustment of the mass sensor is indicated below.

Example Output (1)

When "8. Internal Settings" - "InFa(GLP output)" is set to " !: #LL INL"



. : Space: ASCII 20h <TERM> : Terminator: C_R L_F

C_R : Carriage return: ASCII 0Dh L_F : Line feed: ASCII 0Ah

- 1 Manufacturer name
- 2 Model name
- 3 Serial number
- 4 ID
- 5 Date
- 6 Time

- 7 Sensitivity adjustment (mass sensor)
- 8 Weight value
- 9 Remarks space*1
- 10 Signature space*1


^{*1} Refer to "9.3.2. Description of Printed Information"

9.3.5. Output for Heating Temperature Adjustment

The GLP output when performing adjustment of the heating temperature is indicated below.

Example Output

When "8. Internal Settings" - "InFa(GLP output)" is set to " : FLL INE"



: Space: ASCII 20h <TERM> : Terminator: C_R L_F

C_R : Carriage return: ASCII 0Dh L_F : Line feed: ASCII 0Ah

- 1 Manufacturer name
- 7 Sensitivity adjustment (heating temperature)

2 Model name

- 8 Target temperature: 100°C
- Actual temperature (corrected
- input temperature)

- 3 Serial number
- 9 Target temperature: 160°C input temperature)
- Actual temperature (corrected
- 10 Remarks space*1
 11 Signature space*1
- 5 Date6 Time

4 ID


^{*1} Refer to "9.3.2. Description of Printed Information"

10. Data Memory Function

- The data memory function automatically records the measurement results when measurement is complete.
- Up to 200 sets of data can be recorded.
- The recorded measurement results can be output to the AD-8127 (multi printer) or AD-8129TH (thermal printer) or imported to a computer using the communication software (WinCT).
- The recorded measurement results can also be erased.
- You can select either " ∤ (record)" or "♬ (do not record)" for the "data memory function (ຝ ฅ ೬ ฅ)" in "8. Internal Settings".
- **MEM** is displayed when the data memory function is enabled.
- If FUL is displayed, new results cannot be recorded unless existing results are erased.
- To record measurement results, make sure to enable the data memory function before performing measurement.

CAUTION

• If the data memory function is used to display the mass, the data number (**MEM**) is prioritized over the program number (**PROG**).



10.1. Preparations

Enabling the Data Memory Function (Changing the Internal Settings)

Step	Description	Display and key operation
1.	Press and hold the SELECT key (for approx. two seconds) with the mass displayed to display the "8. Internal Settings" menu.	Long press (for approx. two seconds)


Step	Description	Display and key operation
2.	Press the SELECT key several times to match the display with the figure.	(SELECT)
		Press several times
		dout
3.	Press the ENTER key.	PRINT /ENTER
		° KEŸ
4.	Press the SELECT key to display the "dRtR (data memory function)" item.	SELECT
		° ° FF
5.	Press the ↑ or ↓ key to set "d用上用 (data memory function)" to " the (enabled)".	
		O N
6.	Press the ENTER key to register the change.	PRINT /ENTER
		U5b

10.2. Batch Output of Recorded Results

CAUTION

• With the default internal settings, the "data output interval (PUSE)" is set to "no interval (PUSE = \square)". If the printer set as the output destination requires an interval, refer to "8. Internal Settings" to change to "about a 1.6 second interval (PUSE = !)".

Step	Description	Display and key operation
1.	Press and hold the ENTER key (for approx. two seconds) with the mass displayed.	PRINT /ENTER SET TIME
2.	Press the SELECT key several times to display மம는, as required. *When GLP output is enabled (when " '피투ㅁ (GLP output)" is set to "건" or "석"), ఓ '5분 and 5 '년 are also displayed.	Press several times
3.	Press the ENTER key. *If the measurement result has not been saved, No dfleft is displayed.	PRINT JENER
4.	Press the SELECT key.	SELECT SELECT



Example Output

With data memory output, the data is output in a format like the following.

```
PROGRAM
          No.
PROGRAM ID
        P 001
MODE
        STANDARD
            MID.
DRYING STANDARD
          180 C
OFFSET
         1.23 %
RESULT
        MOIST /W
        7.692 %
JUDGMENT
              0K
DATE 2024/02/14
TIME
        19:15:57
```

10.3. Batch Erasure of Recorded Results

10.		
Step	Description	Display and key operation
1.	Press and hold the ENTER key (for approx. two seconds) with the mass displayed.	PRINT
2.	Press the SELECT key several times to display CLr, as required.	SELECT
	*When GLP output is enabled (when " ˌnF a (GLP output)" is	Press several times
	set to "건" or "꾹"), ᇈ ɹ5분 and 5 ជ are displayed.	EL-
3.	Press the ENTER key.	ARER PRINT /ENTER
		[Lr No
4.	Press the SELECT key.	SELECT SELECT
		[Lr <u>Ç</u> o

Step	Description	Display and key operation
5.	Press the ENTER key. All the recorded data is deleted.	PRINT /ENTER
6.	When the process is complete, the product automatically returns to the mass display. The data number is reset to zero.	End MEM. NODE MITTEN SET 1996. 9 5 b d Partien SET 1996. 0.0000 g

11. Password Function

The password function enables the use of the moisture analyzer and its functions to be restricted.

This is useful for preventing modifications to the date and time settings and changes to the internal settings by non-administrator users.

Enter one of five keys four times for the password.

This allows for $5 \times 5 \times 5 \times 5 = 625$ combinations.

Five keys: PROGRAM, ↓, ↑, SELECT, and ENTER

The password function is disabled by default.

Enable/disable the password function and enter the password in "8. Internal Settings".

"PW (the password function)" in "PR55wd (password)" can be set to one of three values in "8. Internal Settings".

Set value	Function	
PW = 🖫	No password function	
PW = ;	Request password entry to use the moisture analyzer	
PW = 2	Request the administrator password to log in when changing settings	

PW = 7 No password function

The password function is not used.

Anyone can measure moisture content.

All functions can be used.

Settings can also be changed.

PW = ! Request password entry to use the moisture analyzer

The administrator (RIM IN) can set a unique password to restrict the users of the moisture analyzer.

The default administrator (PIM IN) password is "PPPP" (PROGRAM key four times).

Password entry is required to display the mass with the RESET key when the display is off.

The moisture analyzer cannot display the mass unless the correct password is entered.

Login level	Description
Administrator (R] M , N)	All functions and settings can be used.
Administrator (A 111 TN)	A separate password can be set for 10 users.
User(USER [] to USER [])	Initialization, setting changes (including the clock), mass sensor sensitivity adjustment, heating temperature adjustment, and measurement condition changes are restricted.
No password	The moisture analyzer cannot be used.

PW = 🗗 Request the administrator password to log in when changing settings

With this function, anyone can perform measurement with the moisture analyzer but initialization and setting changes (including the clock) are restricted.

(Password entry is not required to display the mass with the RESET key when the display is off.)

There are two login levels: administrator (AM N) and guest (LUE5L).

Login level	Description
Administrator (月 🛮 M ,N)	All functions and settings can be used.
Guest(『UE5』) No password*1	Initialization, setting changes (including the clock), mass sensor sensitivity adjustment, heating temperature adjustment, and measurement condition changes are restricted.

^{*1} If you log in by pressing the RESET key while holding the STOP key with the display off, administrator (月 🛚 🐧 , N) password entry is requested.

Items Limited by Login Level

, ,	Login level		
Item	Administrator	User	Guest
	(A DM ·N)	(USER 01 to 10)	(GUESt)
Password entry (when logging in)		Required	Not required
Mass sensor sensitivity adjustment/heating temperature adjustment	Yes	No	
Changing internal settings (time/date settings, etc.)	Yes	No	
Changing the measurement conditions	Yes	No *2	
Changing the program number	Yes	Yes *2	
RsTemp (moisture analyzer unit)	Yes	No	
RsTemp (computer software)	Yes	Yes	

^{*2} A program number can be used to select an arbitrary measurement condition from among multiple measurement conditions.

Individual measurement conditions cannot be changed because the functionality is restricted.

11.1. Preparing the Password Function

PW (the password function) in "PR55 $_{W}d$ (password)" can be "enabled (PW = $_{*}t$ or $_{*}Z$)" or "disabled (PW = $_{*}U$)" in "8. Internal Settings".

Procedure

Step	Description	Display and key operation
1.	Press and hold the SELECT key (for approx. two seconds) with the mass displayed to display the "8. Internal Settings" menu.	Press and hold (for approx. two seconds)
2.	Press the SELECT key several times to match the display with the figure.	Press several times PRSSwd
3.	Press the ENTER key to display the "PW (password function)" item. (Press the RESET key to cancel.)	PRINT
4.	Press the	Press several times PH Or PH FIC

Step	Description	Display and key operation
5.	Press the ENTER key to match the display with the figure. (No flashes while No is selected)	PRINT /ENTER
6.	Press the SELECT key to switch YE5 / No so that YE5 flashes.	SELECT SUPE YES NO
7.	With YES selected, press the ENTER key to enable the password function.	PRINT /ENTER SURE SURE SURE B of d
8.	The screen changes to that indicated in the figure. To cancel registration (modification), press the RESET key twice to return to the mass display. To register (change) the password, proceed to step 5 of "11.2. Registering (Changing) the Password".	PRSSNO. ON:OFF /RESET Press twice PROG MODE PATTERN SET HAMP. ACCURACY TARGET SUBSTITUTE SUBSTIT

11.2. Registering (Changing) the Password

The password can be registered or changed in "PRSS N_{\square} (register password)" in "PRSS $_{\square}$ (password)" in "8. Internal Settings".

CAUTION

- The RESET key can be pressed and held (for approx. two seconds) to turn the display off (log out).
- When set to Lock = ₹, administrator (₽ ₪ , N) password entry is required to log in as the administrator. Password entry is not required for users (U 5 € ₽ □ 1 to U 5 € ₽ 1□).
- The moisture analyzer will not be able to use if the password is forgotten. Make a record of the registered password and store/manage it appropriately.
- The same password as that registered for the administrator ($R \ \square M \ , N$) cannot be registered for users ($U \ S \ E R \ \square I$ to $U \ S \ E R \ I \ \square$).
- For information on deleting a password, refer to "11.5. How to Delete a User (USER) Password".

How to Register (Change) the Password

1100	How to Register (Change) the Password		
Step	Description	Display and key operation	
1.	Press and hold the SELECT key (for approx. two seconds) with the mass displayed to display the "8. Internal Settings" menu.	Press and hold (for approx. two seconds)	
2.	Press the SELECT key several times to match the display with the figure.	PRSS wd	
		טאננווי	
3.	Press the ENTER key to display the "PW (password function)" item.	PRINT /ENTER	
4.	Press the SELECT key.	PASSNo.	

Step	Description	Display and key operation
5.	Press the ENTER key to display the login level (P IM IN).	PRINT /ENTER PRINT /ENTER
6.	Press the SELECT key to display the login level to change. In this example, display administrator (A IM IN). "O (the safety icon)" lights for login levels which already have a password registered. The password can be changed.	Press several times USRE 01 to USRE 10
7.	Press the ENTER key on the login level to register (change) the password of. In this example, change the password of the administrator (R IM IN).	PRINT /ENTER
8.	The current password is displayed. (The default administrator (月 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1	ĎPPP PW
9.	Perform the following key operation to enter the four digit password. If no key operations are performed for 10 minutes, the screen automatically returns to the login level display. PROGRAM key ··· input P key ··· input I key ··· input I SELECT key ··· input 5 ENTER key ··· input E RESET key ··· go one character back No key operations for 10 minutesscreen automatically returns to login level display	PROGRAM SELECT PRINT /ENTER

Step	Description	Display and key operation
10.	The new password is displayed after pressing the key four times.	DUSE PW
11.	Press the SELECT key to switch YES / No so that YES flashes.	SURE SELECT
12.	With YES selected, press the ENTER key to register the password.	PRINT /ENTER SUPE SUPE
13.	When configuration is complete, the next login level is displayed. To continue configuration, repeat the procedure from step 6.	USRE O I
14.	To finish configuration, press the RESET key three times to return to the mass display.	Press three times Std Martin St Table S.C.

11.3. How to Log In

Logging In as the Administrator ($RDM \cdot N$) or a User ($USER \cdot D \cdot I$ to $USER \cdot ID$)

If PW (the password function) in PRSSMd (password) is set to PW = 1 (enabled: restrict use of moisture analyzer) in "8. Internal Settings", password entry is required when logging in.

2. Password entry 3. Perform the foll digit password. If no key opera the screen auto	lowing key operation to enter the four tions are performed for 10 minutes, omatically turns off.	Display and key operation SLEEP ON:OFF /RESET /IN USER PROGRAM
2. Password entry 3. Perform the foll digit password. If no key opera the screen auto	y is displayed. Ilowing key operation to enter the four are performed for 10 minutes, omatically turns off. [] key ···· input P	USER PW. YIV
3. Perform the foll digit password. If no key opera the screen auto	lowing key operation to enter the four tions are performed for 10 minutes, omatically turns off.	PW. Y
digit password. If no key opera the screen auto	tions are performed for 10 minutes, omatically turns off. key ···· input P	PW. X
SELECT ke	·········input ∄ ········input ∄ ey······· input 5 y······· input <i>E</i> y······· go one character back performed for 10 minutes display off	ON:OFF /RESET
the entire displato the mass displays to the mass displays the pass of the administration (The default and PPPP" (PROC	word of the administrator to log in as for. dministrator password is set to " GRAM key four times).) wrong password, a buzzer sounds h FR IL displayed, then the	Password matches Password does not match PAIM IN FRIL Buzzer × 3 Display off Mass display

Logging In as a Guest ([UE5])

If "PW (the password function)" in "PR55wd (password)" is set to "PW = (anabled: moisture measurement available)" in "8. Internal Settings", password entry is not required when logging in.

Step	Description	Display and key operation
1.	Press the RESET key with the display off. (Refer to "11.4." to switch to the display off state.)	SLEEP ON:OFF /RESET
2.	The screen switches to that indicated in the figure, then switches to the mass display.	PRODUMEN MODE MATIEM SET TEMP

Logging In as the Administrator (RDM IN)

	Logging In as the Administrator (ฅև៣ ៲៧)			
Step	Description	Display and key operation		
1.	With the display off, press the RESET key while holding the STOP key. (Refer to "11.4." to switch to the display off state.)	STOP + ON:OFF /RESET		
2.	Password entry is displayed.	PW. 1		
3.	Perform the following key operation to enter the four digit password. If no key operations are performed for 10 minutes, the screen automatically turns off. PROGRAM key ··· input P key ··· input II SELECT key ··· input II SELECT key ··· input E RESET key ··· go one character back No operations performed for 10 minutes display off	PROGRAM PROGRAM SELECT PRINT /ENTER		
4.	If the password matches, the login level is displayed, the entire display lights up, then the screen switches to the mass display. Enter the password of the administrator to log in as the administrator. (The default administrator password is set to "PPPP" (PROGRAM key four times).) If you enter the wrong password, a buzzer sounds three times with FRIL displayed, then the display turns off.	Password matches Password does not match Password matches Password does not match FRIL Buzzer × 3 Display off Mass display		

11.4. How to Log Out

Step	Description	Display and key operation
1.	The RESET key can be pressed and held (for approx. two seconds) to log out and turn the display off.	PROO MODE PATTERN SET TEMP. ACCURACY TARGET S.U.g.
	The display is dark when it is off.	
	When $PW = 1$, password entry is required to display the mass again if the display is off.	ON:OFF /RESET
	If "♬ - □ F F (auto power off)" is set to "♬ - □ F F = ;	
	(enabled)" in "bfffnc" (environment/display)" in the internal settings, the display will automatically turn off if no operations are performed for 10 minutes.	SLEEP

11.5. How to Delete a User (USER) Password

CAUTION

• The administrator (PIM IN) password cannot be deleted. Refer to "11.2. Registering (Changing) the Password" to change it to a password of your choice.

How to Delete a Password

Step	Description	Display and key operation
1.	Press and hold the SELECT key (for approx. two seconds) with the mass displayed to display the "8. Internal Settings" menu.	Press and hold (for approx. two seconds)
		b85Fnc
2.	Press the SELECT key several times to match the display with the figure.	Press several times PRSSwd
3.	Press the ENTER key to display the "PW (password function)" item.	PRINT /ENTER OFF

Step	Description	Display and key operation
4.	Press the SELECT key to match the display with the figure.	PASSNo.
5.	Press the ENTER key to display the login level (P IM IN).	PRINT /ENTER
		PA DM IN
6.	Press the SELECT key to display the login level to change. In this example, display #5EP [] (user 01).	SELECT Press several times
	"O (the safety icon)" lights for login levels which already have a password registered.	°USER OI
7.	Press the ENTER key. The current password is displayed.	SELECT JUSE PW
8.	Press and hold the RESET key (for approx. two seconds) while entering the password to match the display with the figure.	Press and hold (for approx. two seconds)
9.	Press the ENTER key to match the display with the figure.	PRINT /ENTER
10.	Press the SELECT key to switch [] / N .	EL , ,

Step	Description	Display and key operation
11.	With in flashing, press the ENTER key to delete the password.	PRINT /ENTER
		End
		USER OI

11.6. If the Administrator (ADMIN) Password Is Forgotten

The moisture analyzer will not be able to use if the password is forgotten.

To cancel the password, the product must be returned to A&D for a repair. Request a repair.

12. Interface Specifications


12.1. USB

Connector Type-C (female)

Standard USB 2.0

Device class HID (human interface device): Quick USB

CDC (communication device class): Virtual COM



CAUTION

- Power cannot be supplied from a USB AC adapter or mobile battery.
- Do not connect a USB AC adapter or mobile battery, as doing so may cause product failure.
- USB Type-C USB memory cannot be used.
- Power cannot be supplied to external devices from the moisture analyzer.

12.2. RS-232C

Connector 9-pin D-Sub (male)
Communication EIA RS-232C

method

Communication Bidirectional asynchronous communication method

format


Data transfer rate Approx. 5 times/second

Signal format Baud rate 2400 bps

Data bits 7 bits
Parity Even
Stop bits 1 bit


Encoding ASCII encoding

One character format




9-pin D-Sub pin layout

Pin no.	Signal name	Direction	Description/Remarks
1	-	-	Same potential as SG*1
2	TXD	Output	Sent data
3	RXD	Input	Received data
4	-	-	N.C.
5	SG	-	Signal ground
6	DSR	Output	Data set ready
7	RTS	Input	Request transmission
8	CTS	Output	Allow transmission
9	-	Output	12 V output*1



Signal names other than TXD and RXD are the names on the DTE side.



*1 Used for some A&D peripherals. Do not wire these pins when connecting to a device from another manufacturer where power is output. Make sure to use a compliant cable, as using an incorrect connection cable may damage the device.

13. Connecting to a Peripheral

You can use the standard RS-232C connector and USB Type-C connector of the moisture analyzer to connect to a peripheral, computer, or device such as a PLC.

13.1. Cables Used for Connecting to a Peripheral

"Cables used for connecting to peripherals" indicates the connection cables compliant with the interfaces used with peripherals.

Cables used for connecting to peripherals

Periph	eral	Communication	Connection c		
Product name	Product code	interface used		Cable product code	Remarks
Multi printer	AD-8127		[Included as standard]		
Thermal printer	AD-8129TH	RS-232C	RS-232C cable included with printer	AX-KO2741-100	
			[Sold separately]		*1
Computer		USB	[Included as standard] *2 USB cable included with moisture analyzer	AX-KO7919-200	

^{*1} Uses AX-USB-9P, AD-8541-SCALE, and AD-1688 to connect with the computer.

When exchanging data, the connection cable included with these products can be used.

^{*2} UL certified products do not include a USB cable.

13.2. Printing Mass and Moisture Content Values to a Printer

The table below indicates internal settings of the moisture analyzer and example printer settings for printing data such as the moisture content.

13.2.1. For the AD-8127 or AD-8129TH

- The standard RS-232C interface can be used to print measurement results and sensitivity adjustment records supporting GLP/GMP/ISO to a multi printer (AD-8127) or thermal printer (AD-8129TH).
- The functions of the AD-8127 or AD-8129TH can be used to print changes in the moisture content over a fixed period of time and the results of processing statistics about the measurement results.
- Use the cable included with the AD-8127 or AD-8129TH to connect.

Setting correspondence chart

How to use	Internal settings of moisture analyzer			AD-8127 setting	
now to use	PrE	5 - 4	PUSE	inFo	PRN MODE
Print measurement results including measurement conditions (non-statistical computation)	[], (Ü	Ü	6 Z 3, 4	DUMP Dump print mode
Print measurement results (statistical computation)	I I, 1	Ü	Ü	Ü	EXT.KEY External key print mode
Output changes in moisture content	2		Ę	Ü	TIMER Interval print mode
GLP/GMP/ISO compatible printing	I I, 1	Ü	ij.	1, 2, 3, 4	DUMP Dump print mode
Output measurement data with data memory function	[], (Ü	Č3	0, 1, 2, 3, 4	DUMP Dump print mode

For details on the settings, refer to "8. Internal Settings" and the instruction manual of the printer.

13.3. Connecting to a Computer

13.3.1. Virtual COM Mode

The virtual COM mode function enables you to use the included USB cable *1 to connect the moisture analyzer to a computer and create a COM port on the computer to perform bidirectional communication. Operating systems from Windows XP and later are supported. With Windows 10 and Windows 11, the driver is automatically installed. If the driver is not automatically installed, refer to the PDF file in "Driver for Virtual COM Mode-" on the A&D website (https://www.aandd.jp).

By selecting the COM port in software such as the WinCT-Moisture data communication software, you can perform communication equivalent to RS-232C.

With the virtual COM mode, it is not necessary to configure the baud rate, data bit, parity, and stop bit of the data communication software.

*1 UL certified products do not include a USB cable.

CAUTION

- It may take some time to install the driver for the virtual COM mode for the first time.
- The output format is fixed to the standard A&D format.

How to Use

In this example, the **ENTER** key or a data request command from a computer is used to output the mass value and moisture content from the moisture analyzer.


Switching the USB Operation Mode (Changing the Internal Settings) Switch to the virtual COM mode ($UF_{DC} = I$) (for bidirectional communication).

Step Description Display and key operation Press and hold the SELECT key (for approx. two seconds) 1. 5 E d with the mass displayed to display the "8. Internal Settings" menu. Press and hold (for approx. two seconds) 685Fnc 2. Press the SELECT key several times to match the display with the figure. Press several times 115b

Step	Description	Display and key operation
3.	Press the ENTER key.	PRINT /ENTER
4.	Press the \uparrow or \downarrow key to switch the value of the " $\!$	UFnc C C M
5.	Press the ENTER key when the screen switches to that indicated in the figure to register the settings.	PRINT /ENTER
6.	Press the RESET key to return to the mass display.	ON:OFF /RESET FROM MODE MATTERN SET TEMP. 1 1 5 c USB O O O O O O O O O O O O O

Output Method

	ut Method	Dieploy and key are satisfa
Step	Description	Display and key operation
1.	Use the USB cable included with the moisture analyzer *1 to connect the moisture analyzer to the computer. When connecting for the first time with Window 10 or Windows 11, the computer will automatically start installing the driver. With an operating system other than Windows 10 or	PROG NOBE NITION SET TIME S.G. ACCURACY LARGET S.G. S.G. S.G. S.G. S.G. S.G. S.G. S.G
	Windows 11, the driver must be manually installed. For information on installing the driver, refer to the PDF file in "Driver for Virtual COM Mode-" on the A&D website (https://www.aandd.jp). *1 UL certified products do not include a USB cable.	
2.	When the moisture analyzer connects to the computer, USB flashes on the display of the moisture analyzer, as indicated in the figure. (This indicates that communication with the computer is being established.)	SE d MITTEN SET TEMP. 1
3.	When communication is established between the moisture analyzer and the computer, the virtual COM connection is indicated on the display of the moisture analyzer (for approx. two seconds) as indicated in the figure, then the screen automatically switches to the mass display. The "USB" icon (USB connection icon) lights while the product is connected via USB.	Displayed for approx. two seconds St. d
4.	Start the computer software for sending the mass and moisture content values (such as WinCT).	



Step	Description	Display and key operation
9.	Measure the moisture content.	MATIENN H. H 3 % MOJIST
10.	Press the ENTER key on the moisture analyzer or send a data request command from the computer. The moisture content value is output from the moisture analyzer. Example output ST,+00014.43% <term> : Space (ASCII 20h) <term> : Terminator (CR LF) CR : Carriage return (ASCII 0Dh)</term></term>	or Send data request command from computer
11.	To end the procedure, remove the USB cable. When the moisture analyzer disconnects from the computer, the USB connection icon (USB) disappears.	Data output FROG MODE MATTERN SET THAN SET THA

13.3.2. Quick USB Mode

The Quick USB mode enables you to connect the moisture analyzer to a computer via a USB cable to directly input the output of the moisture analyzer to computer software such as Excel or Word. Operating systems from Windows XP and later are supported.

Because the standard Windows driver (HID) is used, a dedicated driver does not need to be installed and communication can be performed simply by connecting the USB cable.

CAUTION

- The quick USB mode performs one-way communication from the moisture analyzer to the computer. Commands cannot be sent from the computer to the moisture analyzer.
- The output format is fixed to the NU2 format.
- Make sure to disable the screen saver and standby mode of the computer.
- Do not use the quick USB mode when the data output mode of the moisture analyzer is set to the stream mode.

Because the stream mode continuously outputs the mass value from the moisture analyzer to the computer, it may cause the computer to operate in an unexpected manner.

How to Use

In this example, the ENTER key is used to output the mass value and moisture content from the moisture analyzer.

Switching the USB Operation Mode (Changing the Internal Settings)

Switch to the quick USB mode (!! F n c = !!) (for one-way communication).

Step	Description	Display and key operation
1.	Press and hold the SELECT key (for approx. two seconds) with the mass displayed to display the "8. Internal Settings" menu.	Press and hold (for approx. two seconds)
2.	Press the SELECT key several times to match the display	(SELECT)
	with the figure.	
		Press several times
		U5Ь
3.	Press the ENTER key.	PRINT /ENTER
		UFnc C M
4.	Press the \uparrow or \downarrow key to switch the value of the " $\!$	UFnc C M

Step	Description	Display and key operation
5.	Press the ENTER key when the screen switches to that indicated in the figure to register the settings.	PRINT /ENTER
6.	Press the RESET key to return to the mass display.	ON:OFF /RESET FROO MODE MATIEN SET TIME SC. S.U. S.U. S.U. S.U. S.U. S.U. S.U.


Output Method

Step	Description	Display and key operation
7.	Use the USB cable included with the moisture analyzer *1 to connect the moisture analyzer to the computer. When connecting for the first time, the computer will automatically start installing the driver.	SED O SIND G
	*1 UL certified products do not include a USB cable.	
8.	When the moisture analyzer connects with the computer, the quick USB connection is indicated on the display of the moisture analyzer (for approx. two seconds) as indicated in the figure, then the screen automatically switches to the mass display. The "USB connection icon (USB)" is lit while the product is connected via USB.	Displayed for approx. two seconds Std Std
9.	Launch the computer software to send the mass and moisture content values to (such as Excel).	
10.	Set the keyboard input mode to half-width input. Values cannot be input correctly if it is set to full-width input.	

Step	Description	Display and key operation
11.	Press the RESET key to reset the display to zero.	ON:OFF /RESET FROO MODE PATTERN SET TEMPS SET OF SET
12.	Place the sample on the sample tray.	PROO MODE PATIENT SET 11M9. 1 5 b d 10 5 c ACCURACY TANGET S.D. S.D. S.D. S.D. S.D. S.D. S.D. S.D
13.	Place the cursor in the location to input the mass value. A B C 1	
14.	Press the ENTER key to send the mass value from the moisture analyzer and input it to the location of the cursor. A B C 1 5.03 2 3	PRINT /ENTER Data output
15.	Measure the moisture content.	IH.H 3 % MOIST
16.	Press the ENTER key to send the moisture content value from the moisture analyzer and input it to the location of the cursor. A B C 1 14.43 2 3 3 3 4 5 6 6 6 6 6 6 6 6 6 6 6 6 6 6 6 6 6 6	PRINT /ENTER Data output
17.	To end the procedure, remove the USB cable. When the moisture analyzer disconnects from the computer, the USB connection icon (USB) disappears.	PROOF MODE PATTERN SET TEMP. USB PROOF MATTERN SET TEMP. ACCURACY TARGET SET TEMP. SET TEMP. ACCURACY TARGET SET TEMP. ACCURACY TARGET SET TEMP. SET TEMP. SET TEMP. ACCURACY TARGET SET TEMP. SET TEMP. SET TEMP. ACCURACY TARGET SET TEMP. SET TEMP. SET TEMP. SET TEMP. ACCURACY TARGET SET TEMP. SET TEM

13.3.3. RS-232C

The RS-232C interface of the moisture analyzer is DCE (Data Communication Equipment) that can connect to a computer. A straight-type RS-232C cable is used to connect. If the computer does not have an RS-232C connector, connect it via the virtual COM mode of a USB connector. (For information on the communication settings, refer to "12.2. RS-232C".)



9-pin D-Sub (female), inch screws

13.4. WinCT-Moisture Communication Software

- WinCT-Moisture is data communication software for Windows that enables the data of the moisture analyzer to be imported to a computer for saving or data analysis.
- WinCT-Moisture can be downloaded from "Software Downloads" on the A&D website https://www.aandd.jp).
- WinCT-Moisture includes two programs: RsFig and RsTemp.

13.4.1. RsFig Graph Software for Moisture Content Measurement


- RsFig is Windows software that enables the data received from the moisture analyzer to be graphed in real-time.
- This enables you to check changes in the moisture content being measured to understand the process by which the moisture content stops changing (the convergence process).
- Graphs can also be overlaid on each other, so when measurement is repeated with different heating temperature conditions, the measurement process can be overlaid on the same graph.
- The measured data can be exported to a CSV file.
- For information on how to change and restrict the settings, refer to the instruction manual for RsTemp (RsFig_ReadMe).

Example display for RsFig

The figure below is an example of overlaying the measurement results for sodium tartrate dihydrate on the graph when the heating temperature is changed by 20°C each time (100 to 200°C).

The horizontal axis is the time elapsed (in minutes) since measurement started and the vertical axis is the moisture content (%).

The mass of the sample will decrease as the water evaporates due to heating, and that decrease in mass is calculated and displayed as the moisture content. When the moisture content stops changing (when the graph becomes flat), that is the moisture content of the sample.



13.4.2. RsTemp Software for Automatic Heating Temperature Detection


- RsTemp is heating temperature detection software that automatically detects the recommended heating temperature when measuring the moisture content of a sample using an A&D moisture analyzer.
- The heating temperature is determined by gradually changing the temperature for heating the sample (in steps) and measuring the moisture content.
- The figure below is an example of measuring a sodium tartrate dihydrate sample with RsTemp.
- The horizontal axis indicates the elapsed time, the red curve in the figure indicates the moisture content, which is the left vertical axis. The green curve in the figure indicates the change in moisture content (%/min), which is the right vertical axis.
- The moisture content is measured with the heating temperature automatically increased by 20°C every five minutes.
- The starting heating temperature, temperature increase per step, and measurement time per step can be adjusted.
- (In the figure, the starting heating temperature is set to 100°C, the temperature increase per step is set to 20°C, and the measurement time per step is set to 5 minutes.)
- The table under the graph indicates the "heating temperature" for each step, the "moisture content" and
 "moisture content change" when measurement stops, and the "recommended temperature level".
 Recommended temperatures are given in six levels of A to F, where A is the temperature deemed to be
 the most recommended.



 For information on how to change and restrict the settings, refer to the instruction manual for RsTemp (RsTemp_ReadMe).

CAUTION

- RsTemp determines the recommended heating temperature based on the measurement and
 calculated result, but the recommended temperature may not be able to be appropriately determined,
 depending on the sample type and amount.
- When deciding the heating temperature of the sample, also observe the state of the sample over time (whether it melts, burns, smells, or disintegrates) and use that information to ultimately help decide the optimal heating temperature.



13.5. WinCT Data Communication Software

- WinCT is data communication software for Windows that enables the mass and moisture content values of the moisture analyzer to be easily imported to a computer. It uses RS-232C for communication.
- WinCT can be downloaded from "Software Downloads" on the A&D website (https://www.aandd.jp).
 For information on installing and setting up WinCT, see "Setting Up WinCT" and "WinCT Instruction Manual".
- WinCT includes three programs: RsCom, RsKey, and RsWeight.

"RsCom"

- Enables the moisture analyzer to be controlled by sending commands.
- Displays the received data and saves it as a text file (.txt).
- Multiple instances can be executed to communicate with multiple moisture analyzers.
- Can be executed at the same time as other applications. (Does not monopolize the computer.)
- Can also receive the GLP output data of the moisture analyzer.

"RsKey"

- Enables the mass and moisture content values of the moisture analyzer to be directly input to another application.
- Any application such as Word or Excel can be used, as long as it allows keyboard input.
- Can also input the GLP output of the moisture analyzer.
- Enables the test display function to be used to use a computer as an external display for the moisture analyzer.

(With the moisture analyzer in the stream mode.)

"RsWeight"

- · Graphs received data in real-time.
- Enables the maximum, minimum, average, standard deviation, and coefficient of variation of the received data to be calculated and displayed.

13.6. Commands

The following commands can be sent from a computer to control the moisture analyzer.

Add a terminator $\frac{C_R}{L_F}$ (0Dh, 0Ah) to the command before sending it to the moisture analyzer.

List of Commands

Command	Description	
Q	Sends one measurement value.	
SIR	Continuously sends measurement values.	
С	Stops continuously outputting measurement values with the SIR command.	
QM	Outputs one measurement value during measurement. QM can only be used during measurement.	
START	Performs the same function as the START key.	
STOP	Performs the same function as the STOP key.	
RESET	Performs the same function as the RESET key.	
ENTER	Performs the same function as the ENTER key.	
SELECT	Performs the same function as the SELECT key.	
DOWN	Performs the same function as the key.	
UP	Performs the same function as the	
PROGRAM	Performs the same function as the PROGRAM key.	

14. How to Check the Software Version of the Moisture Analyzer


The specifications of the product may differ according to the software version of the moisture analyzer. You can follow the procedure below to check the software version.

Procedure for Checking the Software Version

Step	Description	Display and operation
1.	Connect the power cable of the moisture analyzer main unit to the power outlet.	
2.	The LCD of the moisture analyzer will fully light up.	8888 6 8 8 8 8 8 8 8 8 8 8 8 8 8 8 8 8
3.	P-*.*** is displayed for approx. one second. The number in *.*** is the software version.	P - 2.000

15. Maintenance


- Make sure to remove the power plug from the power outlet before performing maintenance.
- Perform operations after confirming that the various parts of the moisture analyzer have cooled down sufficiently.
- The sample tray, tray holder, and breeze break can be removed.
- Remove any dirt using a cloth that has been dampened with water or water containing a small amount of neutral detergent and wrung out well.
- Do not use organic solvents or chemical wipes.
- Perform assembly as described in "4.1. Installing the Moisture Analyzer" and "1. Cautions Regarding Handling" after the parts are completely dry.
- When transporting the product, use the dedicated packaging box.



15.1. Cleaning the Heater

- Clean the glass housing if it gets dirty, or it may not be able to heat properly. The glass housing can be easily detached by removing the two screws.
- Clean the halogen lamp if it has any fingerprints on it, or its life may be shortened.
- Do not touch the metal plate for reflection on the rear of the halogen lamp.
 - Doing so may cause the set temperature of the sample tray and the actual heating temperature to deviate.
- Do not touch the temperature sensor adjacent to the halogen lamp.
 Doing so may cause the set temperature of the sample tray and the actual heating temperature to deviate.





Temperature sensor

Metal plate for

reflection

15.2. How to Replace the Halogen Lamp

If drying takes time because the halogen lamp output has decreased due to lamp degradation or the halogen lamp has stopped lighting, replace the halogen lamp. Use the halogen lamp of accessory AX-MX-34-120V *1 or AX-MX-34-240V that is adapted to your local voltage. The expected life of the halogen lamp is approx. 5,000 hours.

CAUTION

- Performing this procedure without removing the power cable can result in electrocution.
- Read the power supply voltage label on the back of the heater cover and confirm that the rated voltage
 of the halogen lamp is correct for your power supply voltage.

Voltage Label	The Rated Voltage of the Halogen Lamp	Accessory number *1
100 – 120V	AC 120 V	AX-MX-34-120V
200 – 240V	AC 240 V	AX-MX-34-240V

- Do not drop, strike, or damage glass parts including the halogen lamp.
 Doing so may cause it to break and lead to injury due to glass shards.
- The halogen lamp degrades due to contamination on its surface. Do not directly touch the glass of the halogen lamp.
- Dispose of the used halogen lamp as-is.
 Breaking a halogen lamp can cause glass shards to scatter, which may result in injury.
- It is recommended that you replace the halogen lamp once it has reached its rated life.
 Continuing to use it may cause damage to the product.
- *1 UL certified products are 120 V Version only.

Step	Description	Diagram
1.	Remove the power cable from the power outlet.	Power outlet Power plug
2.	Confirm that the rated voltage of the new halogen lamp. The rated voltage is indicated on the edge of the connector and the halogen lamp.	Location of rated voltage
3.	Confirm that the heater has sufficiently	
	cooled.	

Step	Description	Diagram
4.	Remove the two screws of the glass housing.	Screw
5.	Disconnect the connector of the halogen lamp, then remove it from the holder.	Heater Halogen lamp Holder
6.	Load the halogen lamp with the protrusions facing down, as indicated in the figure, then connect the connector.	Protrusions facing down Tab Connector
7.	Hook the lead wire of the halogen lamp on the two tabs (on the left and right).	Lead wire
8.	Secure the glass housing with screws so that it does not pinch the lead wire of the lamp.	Glass housing

15.3. How to Replace the Power Fuse

The fuse inside the power supply may blow to protect the moisture analyzer main unit in cases such as when a power supply with the wrong voltage is connected. If the fuse blows, replace it with a new fuse (AXFST6.3A250V; sold separately).

CAUTION

• Performing this procedure without removing the power cable can result in electrocution.

Step	Description	Diagram
1.	Remove the power cable from the power outlet.	Power outlet Power plug
2.	Remove the power cable from the power inlet of the moisture analyzer.	
3.	Use a flat-head screwdriver to remove the fuse cover on the top of the power inlet. (Insert the flat-head screwdriver under the tab on the bottom of the fuse cover, then prise it open to remove the fuse cover.)	
4.	Remove the fuse from the fuse cover, then visually check whether the fuse has blown, or use a multimeter. If the fuse has blown, replace it with a new fuse (sold separately).	
5.	Place the fuse in the fuse cover, then place the fuse cover together with the fuse into the power inlet.	

15.4. Initializing the Settings

You can initialize the settings of the product to restore the factory defaults.

There are two initialization methods, which initialize different settings.

The initialized settings are as follows.

Item	Initialize (internal settings)	Initialize (all settings)
Mass sensor sensitivity adjustment data	No	Yes
Heating temperature adjustment data	No	Yes
Measurement conditions	No	Yes
Internal settings (excluding the password	Yes	Yes
function)		
ID number	Yes	Yes
Results recorded with the data memory	Yes	Yes
function		

Yes: Initialized
No: Not initialized

15.4.1. How to Initialize (Internal Settings)

Step	Description	Display and key operation
1.	Press and hold the SELECT key (for approx. two seconds) with the mass displayed to display the "8. Internal Settings" menu.	Press and hold (for approx. two seconds)
2.	Press the SELECT key several times to match the display with ",n , t f n c".	Press several times
3.	Press the ENTER key.	PRINT /ENTER
4.	Press the ENTER key.	PRINT /ENTER
5.	Press the ↑ or ↓ key to switch to "[□".	

Step	Description	Display and key operation
6.	Press the ENTER key. Initialization completes in several seconds, and End is displayed.	PRINT PRINT (ENTER (Wait several seconds) End BRSFnc
7.	Press the RESET key to return to the mass display.	ON:OFF /RESET SET HANGE SET HANGE SUBJECT SUB

15.4.2. How to Initialize (All Settings)

Step	Description	Display and key operation
1.	Press and hold the SELECT key (for approx. two seconds) with the mass displayed to display the "8. Internal Settings" menu.	Press and hold (for approx. two seconds)
2.	Press the SELECT key several times to match the display with "int Fnc".	Press several times In IEFnc
3.	Press the ENTER key.	PRINT /ENTER
4.	Press the SELECT key to match the display with "[[r RLL".	Press several times
5.	Press the ENTER key.	PRINT /ENTER

Step	Description	Display and key operation
6.	Press the	
7.	Press the ENTER key.	[Lr Ü̈́o̯
7.	Initialization completes in several seconds, and End is displayed.	EL L L Q
		(Wait several seconds)
		End BRSFnc
8.	Press the RESET key to return to the mass display.	ON:OFF (RESET) 1 5 b d

15.5. Troubleshooting

If the measurement results seem incorrect

- Refer to "7.4. Self-Inspection" to try a self-inspection.
- With the product switched to the mass display, load and unload the Weight height weight to check the repeatability of the mass value. Because a tall Maximum: 26 weight may touch the heater, use as short a weight as possible. When you have no choice but to use a 50 g weight, perform measurement with the heater cover open. Avoid disturbance such as wind when doing so. The maximum height of the weight that can be placed on the sample tray (the height from the sample




tray to the glass housing) is approx. 26 mm.

- · Perform the function tests to check whether the moisture content of the included test samples can be correctly measured (refer to "7.2. Test Sample Function Check").
- Is the moisture analyzer subject to any (air conditioner) wind or vibrations? Place the product on a stable surface and ensure it is not subject to any wind or vibrations.
- Has the measurement sample been appropriately processed? For information on cutting samples with large granules or using a glass fiber sheet, refer to "4.2. Requirements for Ensuring Correct Measurement".
- Has measurement been performed properly? For information on preheating before measurement and replacing the tray during continuous measurement, refer to "4.2. Requirements for Ensuring Correct Measurement ".

If the lamp does not light when measurement starts or it takes time to reach the set temperature

- It normally takes approx. six seconds until the lamp lights after the START key is pressed.
- If the heater cover is open, power is not supplied to the halogen lamp.
- The connector of the halogen lamp indicates the compatible voltage. Confirm that the rated voltage.



- Has the fuse blown? Remove the power plug from the power outlet, then check the fuse of the power inlet on the rear of the main unit. (Refer to "15.3. How to Replace the Power Fuse".)
- Was measurement performed at a low temperature after performing measurement at a high temperature? The lamp will not light if the temperature of the tray is higher than the set temperature.
- Confirm that the tray has sufficiently cooled before performing measurement.
- Otherwise, the halogen lamp may have expired. Check the filament of the lamp, and replace the lamp if necessary. Refer to "15.2. How to Replace the Halogen Lamp".

15.6. Errors Displayed

Errors displayed	Description and remedy
	Overload
E	The sample mass exceeded the allowed range. Reduce the sample. If this error occurs when only the sample tray is loaded, contact A&D for a repair.
	Underload
	The sample is too light. (The output from the mass sensor is too low.)
- E	Place the tray holder and sample tray on the product correctly, then press the RESET key.
	Perform mass sensor sensitivity adjustment.
	If the problem persists, contact A&D for a repair.
	AC power supply voltage error
LoWVolt	Check the power supply voltage. The voltage may drop if a power strip is used to share the power supply with other devices.
	AC power supply frequency error
FrEQErr	Check whether the power supply is appropriate.
	Insufficient sample error when heating starts
Lo San	Increase the amount of sample and perform heating.
SAMPLE "	You can set the amount of sample to an arbitrary value. Refer to "6.4.7. Configuring the Sample Mass".
	Excess sample error when heating starts
SAMPLE SB.	Decrease the amount of sample and perform heating.
SHMPLE	You can set the amount of sample to an arbitrary value. Refer to "6.4.7. Configuring the Sample Mass".
	Unstable measurement value Mass sensor sensitivity adjustment cannot be executed because the
	measurement value is unstable.
	Inspect the area around the tray.
Errorl	Improve the installation environment (vibrations, wind, temperature changes, electrostatic, magnetism, etc.) so that it does not affect the moisture analyzer. The error will automatically clear in 10 seconds.
)APQII	Sample mass setting value error
	The sample mass setting value is incorrect.
Error	Set the upper limit to a value larger than the lower limit.
); <u>(</u>	Comparator setting value error
Error	The comparator setting value is incorrect.
	Set the upper limit to a value larger than the lower limit.
	Self-inspection error
[H no	A self-inspection error occurred. Request a repair.
	Heater cover error
[LoSE	If this error continues to be displayed, a repair is required.

Errors displayed	Description and remedy
[AL E	Mass sensor sensitivity adjustment weight problem (positive) The weight for mass sensor sensitivity adjustment is too heavy. Check the area around the tray. Confirm that the weight for mass sensor sensitivity adjustment is not touching the glass housing of the heater cover and that the mass of the weight for mass sensor sensitivity adjustment is appropriate. Press any key or wait 15 seconds to return to the mass display.
-CAL E	Mass sensor sensitivity adjustment weight problem (negative) The weight for mass sensor sensitivity adjustment is too light. Check the area around the tray. Confirm that the mass of the weight for mass sensor sensitivity adjustment is appropriate. Press any key or wait 15 seconds to return to the mass display.
E-UP	Heating temperature adjustment data input timeout Indicates that there was no temperature input after waiting for five minutes when adjusting the heating temperature. Press any key to clear the error. To adjust the heating temperature, repeat the procedure from the start.
MEM	Full memory The number of results recorded with the data memory function reached the upper limit. Existing results must be erased to record new results. Refer to "10. Data Memory Function".
rtc PF	Internal clock battery error Press any key, then enter the date and time. Refer to "8.4. Checking and Configuring the Date/Time". If the problem persists, request a repair. Internal clock malfunction
rtc Err	Request a repair. Internal error
ErrorO	Turn the power OFF then ON again. If the error occurs again, request a repair.
Error 3	IC error Request a repair.
Error8	
Error9	
Ht Err	Temperature control error Try again after turning the power OFF and waiting for at least 30 minutes. If the error occurs again, request a repair.

16. Disposal

Due to the requirements of the European Directive on Waste Electrical and Electronic Equipment (WEEE) 2012/19/EU, the product must not be disposed of as general waste. Follow the local laws when disposing of the product.

Dispose of the product according to the local regulations on recycling electrical and electronic devices. If you have any questions, contact the relevant local government office. Make sure to convey these disposal requirements if transferring the product to a new owner.

17. Specifications

			MS-74A	MX-53A	MF-53A	ML-53A		
Heating method					400 W ha	logen lamp		
Range of sample tray temperature settings			perature	30°C to 200°C (1°C increments)				
Sample	e tray hea	ating patte	rns	Standard h	eating, slow heati	ng, step heating, r	apid heating	
Heating	g tempera	ature adjus	stment	Available with	separate tempera sold se	ature adjustment k parately)	tit (AX-MXA-43;	
Measu	rable san	nple mass		0.1 g to 71 g		0.1 g to 51 g		
Measu			Sample mass 5 g or more	0.01%	0.02%	0.05%	0.1%	
	oducibility content*1 lard	Sample mass 1 g or more	0.05%	0.1%	0.2%	0.5%		
		Weight		0.0005 g	0.001 g	0.002 g	0.005 g	
Minimu display		Moisture	content	0.001%, 0.01%, 0.1%	0.01%, 0.1%	0.05%, 0.1%, 1%	0.1%, 1%	
, ,		Weight		0.0001 g	0.001 g	0.002 g	0.005 g	
Sample mass required for measurement with an expected moisture content of 1% or less		When the expected moisture content is less than 0.1% Sample mass 20 g or more When the expected moisture content is 0.1% to 0.5% Sample mass 5 g or more When the expected moisture content is 0.5% to 1% Sample mass 2 g or more						
S _e	Mea	Standard	mode	The sample mass and termination value*2 are automatically determined according to the measurement accuracy, then measurement stops when the termination value is reached.				
Measureme	Measurement Standard mode Measurement Custom			Measures moisture content by heating for a certain period of time. (1 to 480 min)				
	ent			Enables the user to configure detailed measurement conditions. Measurement ends when the set termination value*2 is reached.				
nt conditions	Measur	Measurement basis		Moisture content (standard before heating), moisture content (Atro, standard after heating), solids, ratio, grams				
	Recordable measurement conditions		200 sets					
Recordable measurement results (data memory function)		200						
Interfaces RS-232C USB		9-pin D-Sub (male) EIA RS-232C Type-C (female) USB 2.0 HID CDC						
Sample tray dimensions		φ95 mm						
Operating temperature and humidity			d	5°C to 40°C; Humidity: 85% or lower RH (without condensation)				
Usage range				Indoor use only				
Elevation				Maximum: 2000 m				

	MS-74A	MX-53A	MF-53A	ML-53A	
	120 V AC Version 100 V to 120 V, 50/60 Hz, 3A *4				
Dower aupply	240 V AC Version 2		00 V to 240 V, 50/60 Hz, 1.5A		
Power supply	Voltage fluctuations −15%, +10%				
	Power	load A	pproximately 500 V	V *3	
Overvoltage category	II				
Pollution level	2				
Maximum power consumption 500 W					
External Dimensions	215 (W) ×380 (D) × 176 (H)				
Main unit weight	Approx. 6 kg (excluding accessories)				

^{*1} The result of performing preheating then measuring the included test sample (approx. 5 g of sodium tartrate dihydrate) at 160°C with standard heating and the standard mode (MID.) and cooling for 15 minutes at room temperature with the heater cover raised after each measurement.

^{*2} Measurement stops when the time change of the moisture content is at or below the set value.

^{*3} Please confirm that this analyzer is compatible with your local voltage, receptacle type, and power cable.

^{*4} UL certified products are 120 V Version only.

List of Included Accessories


Yes Included as standard; - Available for purchase


	MS-74A	MX-53A	MF-53A	ML-53A
Tray holder	Yes	Yes	Yes	Yes
Breeze break	Yes	Yes	Yes	Yes
Display protective cover	Yes	Yes	Yes	Yes
Power cable	Yes	Yes	Yes	Yes
Ground adapter	Yes	Yes	Yes	Yes
Quick Start Guide	Yes	Yes	Yes	Yes
Warranty card	Yes	Yes	Yes	Yes
Body cover	Yes	Yes	-	-
Test sample*1	Yes	Yes	-	-
Glass fiber sheet	Yes	Yes	-	-
Spoon	Yes	Yes	-	-
Tweezers	Yes	Yes	-	-
USB cable	Yes *2	Yes *2	-	-
Sample tray	× 20	× 20	× 10	× 10
Sample tray handle	× 2	× 2	× 1	× 1
Disposable aluminum tray	× 100	× 100	× 100	× 100


Yes: Included; -: Not included


- *1 30 g of sodium tartrate dihydrate
- *2 UL certified products do not include a USB cable.

17.1. External Dimensions









Unit: mm

18. Accessories (Sold Separately)

Accessory

Name	Number	
Disposable aluminum tray (φ90 mm, set of 100)	AX-MXA-30	
Sample tray (φ90 mm, set of 100)	AX-MXA-31	
Glass fiber sheet φ70 mm (filter paper, set of 100) Use for liquid samples with high surface tension.	AX-MX-32-1	
Glass fiber sheet $_{\varphi}$ 86 mm (glass paper, set of 100) The same as that included with the MS-74A and MX-53A. Use for liquid samples.	AX-MXA-32-2	
Test samples (sodium tartrate dihydrate; 30 g × 12 sets)	AX-MX-33	
Halogen lamp (100 V to 120 V)	AX-MX-34-120V	
Halogen lamp (200 V to 240 V)	AX-MX-34-240V *1	
Sample tray handle (set of two)	AX-MXA-35	
Tweezers (set of two)	AX-MX-36	
Spoon (set of two)	AX-MX-37	
Display protective cover (set of five)	AX-MXA-38	
Body cover	AX-MXA-39	
Mass sensor sensitivity adjustment weight (20 g; OIML F1 class accuracy)	AX-MX-41	
Temperature adjustment kit (with calibration certificate)	AX-MXA-43	
Fuse (T6.3 A 250 V)	AX-FST6.3A250V	

^{*1} UL certified products are 120 V Version only.

List of Accessories Available Separately

AD-8129TH: Thermal printer

- Multifunctional
- □ Statistical computation, calendar/clock function, interval print function (prints at a certain interval from 5 sec to 30 min), chart print function (prints the specified two digits in graph format), dump print mode
- □ 13 × 28 dots; 24 characters per line
- ☐ Thermal paper AX-PP147-S (57.5 mm (W) × approx. 30 m)

 Dust-free thermal paper AX-PP183-S (57 mm (W) × approx. 25 m)

AD-1687: Environment logger

☐ Four environment sensors (temperature, humidity, air pressure, and vibration) are included to enable simultaneous measurement and recording with standalone operation. By connecting with the RS-232C output of the moisture analyzer, the mass value can be recorded together with the environment data. Dedicated data importing software is not required.

	-1688: Measurement data logger Enables data output from the RS-232C port to be recorded. This enables mass and moisture content values to be saved in environments where a computer cannot be used. Dedicated data importing software is not required.
	-8526 : Ethernet converter Enables management of measurement values using an Ethernet network, via a LAN port and the RS 232C port of a measurement device. Includes "WinCT-Plus" data communication software
	-USB-9P : USB converter Enables serial communication software such as "WinCT" to be used with a USB connection, even on computer without a COM port. Bidirectional communication can be performed after the driver is installed.
	-KO2741-180 : 1.8 m RS-232C cable (9-pin D-Sub (female) to 9-pin D-Sub (female)) A cable for connecting the moisture analyzer to a PLC, etc.
	-KO7919-200: 2 m USB cable (Type-A to Type-C) The USB cable included with the moisture analyzer as standard. *1 *1 UL certified products do not include a USB cable.
	-1683A: Ionizer Prevents measurement error caused by static electricity during measurement via static elimination. Optimal for precise measurement of samples such as powders because it is a direct flow-type ionize that does not emit wind. It is compact and lightweight.
AD	-1684A: Non-contact electrostatic measuring instrument Displays the result of measuring the charge (of an automatic measurement line, etc.) of moisture analyzer peripherals such as the measured sample, tare, or breeze break. AD-1683A (static eliminator) can be used to remove an electrostatic charge from the product.
	-1689: Tweezers for analysis operations Tweezers for retaining the 1 g to 500 g weight used for the mass sensor sensitivity adjustment of the moisture analyzer.
	The tweezers are 210 mm long and feature a cap on the end.
	-TWEEZERS-25: Tweezers for analysis operations Tweezers for retaining the 1 g to 500 g weight used for the mass sensor sensitivity adjustment of the moisture analyzer. The end features a cap made of polycarbonate + 10% carbon + 10% glass fiber materials, which makes it less susceptible to electrostatic.

а

AD-1603-20F1: Mass sensor sensitivity adjustment weight

☐ A 20 g OIML shape F1 class weight.

AD-8541-PC: Bluetooth® dongle for connecting a computer

□ Enables bidirectional communication between the AD-8541-SCALE and a computer via the COM port using Bluetooth.


Maximum communication distance: Approx. 10 m (For details, refer to "AD-8541-PC Instruction Manual".)

AD-8541-SCALE: Bluetooth® converter for connecting a scale

□ Enables wireless communication via Bluetooth with a Bluetooth device such as a smartphone/tablet, computer, external Bluetooth display, or the AD-8931-JA or AD-8541-PC.

Maximum communication distance: Approx. 10 m

(For details, refer to "AD-8541-SCALE Instruction Manual".)





A&D Company, Limited

3-23-14 Higashi-Ikebukuro, Toshima-ku, Tokyo 170-0013, JAPAN Telephone: [81] (3) 5391-6132 Fax: [81] (3) 5391-1566

A&D ENGINEERING, INC.

Headquarters Office: 4622 Runway Boulevard, Ann Arbor, Michigan 48108, U.S.A. Sales Office: 47747 Warm Springs Boulevard, Fremont, California 94539, U.S.A.

Tel: [1] (800) 726-3364 Weighing Support: [1] (888) 726-5931 Inspection Support: [1] (855) 332-8815

A&D INSTRUMENTS LIMITED

Unit 24/26 Blacklands Way, Abingdon Business Park, Abingdon, Oxfordshire OX14 1DY United Kingdom

Telephone: [44] (1235) 550420 Fax: [44] (1235) 550485

A&D AUSTRALASIA PTY LTD

32 Dew Street, Thebarton, South Australia 5031, AUSTRALIA Telephone: [61] (8) 8301-8100 Fax: [61] (8) 8352-7409

A&D KOREA Limited

한국에이.엔.디(주)

서울특별시 영등포구 국제금융로6길33 (여의도동) 맨하탄빌딩 817 우편 번호 07331 (817, Manhattan Bldg., 33. Gukjegeumyung-ro 6-gil, Yeongdeungpo-gu, Seoul, 07331 Korea) 전화: [82] (2) 780-4101 팩스: [82] (2) 782-4264

OOO A&D RUS

ООО "ЭЙ энд ДИ РУС"

Почтовый адрес:121357, Российская Федерация, г. Москва, ул. Верейская, дом 17 Юридический адрес: 117545, Российская Федерация, г. Москва, ул. Дорожная, д.3, корп.6, комн. 86 (121357, Russian Federation, Moscow, Vereyskaya Street 17) тел.: [7] (495) 937-33-44 факс: [7] (495) 937-55-66

A&D Instruments India Private Limited

ऐ&डी इन्सद्रयमेन्द्रस इण्डिया प्रा० लिमिटेड

D-48, उद्योग विहार , फेस –5, गूड़गांव – 122016, हरियाणा , भारत (D-48, Udyog Vihar, Phase-V, Gurgaon – 122016, Haryana, India) फोन : [91] (124) 4715555 फैक्स : [91] (124) 4715599

A&D SCIENTECH TAIWAN LIMITED.

艾安得股份有限公司

台湾台北市中山區南京東路 2 段 206 號 11 樓之 2

(11F-2, No.206, Sec.2, Nanjing E.Rd., Zhongshan Dist., Taipei City 10489, Taiwan, R.O.C.)

Tel: [886](02) 2322-4722 Fax: [886](02) 2392-1794

A&D INSTRUMENTS (THAILAND) LIMITED บริษัท เอ แอนด[์] ดี อินสทรูเม[้]นท[์] (ไทยแลนด[์]) จำกัด 168/16 หม[ี]ที่ 1 ตำบลรังสิต อำเภอธัญบรี จังหวัดปทมธานี 12110 ประเทศไทย

(168/16 Moo 1, Rangsit, Thanyaburi, Pathumthani 12110 Thailand)

Tel: [66] 20038911